

City of White House Public Buildings ADA Inventory

Facility/Parking/Sidewalks

Facility	Location	Observed Deficiency	Suggested Upgrade	Notes	Completion Date
White House Inn Museum		Paint has faded on accessible spaces	Repaint lines		Completed
White House Inn Museum		No signs posted	Install signage at each		Completed
White House Inn Museum		Main entrance is not accessible and has no signage indicating direction to accessible entrance	Evaluate main entrance for accessibility; Install signs along route and at entrance directing to accessible entrance.		Completed
White House Inn Museum	Restrooms	No accessibility signage for 2 restrooms	Install signage or placarding		Completed
Fire Station #2		No van accessible signage	Install required signage (add to existing)		Completed
Fire Station #2		No van accessible signage	Install required signage (add to existing)		Completed
Fire Station #2	Training Room	Room sign is located above door, not accessible; no braille, no raised lettering; not located on latch side of door.	Relocate new tactile signage		Completed
Fire Station #2	Restrooms	Doors are not self-closing (applied to outer door if no stall door)	Add auto closer		Completed
Fire Station #2	Water Fountains	One fountain should be for standing persons, spouts too low.	Adjust one fountain/spout height		Completed
White House Police Department	Parking Lot	No van accessible signage	Install required signage (add to existing)		Completed
White House Police Department		Ramp from accessible aisle has >8.3% running slope	Install detectable warning surface at ramp		Completed
White House Museum				Compliant facility	N/A
White House Inn Museum	Parking Lot and Entry Approach			Parking lot to be repaved. New layout needs to assure compliant spaces and accessibility to entrance.	Completed
White House Inn Museum		No van accessible space	Reconfigure by repainting lines		Completed
White House Inn Museum		Accessible spaces not located nearest to entrance	Relocate close to entrances; see upgrades noted above		Completed
White House Inn Museum		Entry ramp handrail does not extend 12" past ends of ramp	Evaluate circulation path and extend if possible		
White House Inn Museum		No landing at accessible entrance; no maneuvering clearance.	Reconfigure entry to provide required spacing, add automatic door opener.		
Fire Station #1	Parking Spaces	No accessible spaces	At least one accessible space should be added	Not open to public unless by appt.	Completed
Fire Station #2	Rear Parking Lot	Paint has faded on accessible spaces	Repaint lines		Completed
Fire Station #2	Front and Side Parking	Paint has faded on accessible spaces	Repaint lines		Completed
Fire Station #2		Only one ramp adjoining accessible aisles to path	Create accessible ramp from each aisle to path		Completed
White House Police Department		Ramp from accessible aisle has >8.3% running slope	Regrade ramp		Completed

City of White House Public Parks-Trails ADA Inventory

Park/Greenway/Parking/Sidewalks

Facility	Location	Observed Deficiency	Suggested Upgrade	Notes	Completion Date
North Wood Park	Play Area	2 benches are not compliant (access, height and width)	Replace benches with compliant ones		
W.L. Anderson Sports Complex	Sidewalk to fence around field	silt and gravel on path near fence	keep path stable and firm-maintenance		Completed
W.L. Anderson Sports Complex	Pavilion Restrooms	Paper towel and soap dispensers exceed 44" to 48" height	Adjust dispenser height	Hand dryers are compliant	
White House Greenway	James K. Polk Trailhead	Non-accessible portajohns	Replace		
White House Greenway	Honey Run Creek Trailhead	Non-accessible portajohns	Replace		
White House Municipal Park	Play area on west side of Stadium Dr.	7 benches around play area not compliant	Replace benches with compliant ones		
White House Municipal Park	Sidewalk surrounding play area	Silt and gravel on path	keep path stable and firm-maintenance		
White House Municipal Park	Large parking lot east side of Stadium Dr.	2 accessible spaces near basketball court, no signs posted	Install signage at each		
White House Municipal Park		Viewing benches should have back rests	Replace benches with compliant ones		
White House Municipal Park	Restroom Building Near Field No. 5	Signage located on doors instead of Latch side wall, no braille	Replace and relocate signs		
White House Municipal Park	Blue play area on east side of Stadium Dr.			Compliant	N/A
North Wood Park	North Wood Dr. road access	No accessible space	If practical, configure ADA space along street	Street parking only	
North Wood Park	North Wood Dr. road access	Ramp from street not compliant (slope, changes in level, DWS)	Replace ramp		Completed
North Wood Park	Play Area	No access to play area, 8" high timber border surrounds	Include ADA access/upgrades when improved		
North Wood Park	Play Area	Restricted accessible play area due to mulch covering	Modify access routes or resurface play area		
White House Greenway	Greenway-Trail			Upgrade to ADA only if altered or new	
White House Greenway	Andrew Jackson Trailhead	Sidewalk discontinuities near trailhead sign	Evaluate for re-surfacing		
White House Greenway	Tyree Springs Trailhead	No access aisle for accessible space	Reconfigure by repainting lines		
White House Greenway	Tyree Springs Trailhead	No access ramp to trail	Install Ramp		
White House Greenway	Veterans Memorial Trailhead	Water fountain not accessible/knee space	Replace fountain		
White House Greenway	Honey Run Creek Trailhead	Sidewalk discontinuities near trailhead sign	Evaluate for re-surfacing		
White House Municipal Park	Sidewalk to pavilion #1 from small lot	Cross slope near water fountain exceeds 2%	Regrade to required slope		
White House Municipal Park	Parking east side of Stadium Dr.	Accessible spaces not located near ramp or access areas	Relocate close to entrances		
White House Municipal Park	Small pavilion #2 east of Stadium Drive	Picnic table not accessible	Replace table		
White House Municipal Park	Play area on west side of Stadium Dr.	Restricted accessible play area due to mulch covering	Modify access routes or resurface play area		
White House Municipal Park	Water fountain	Not accessible from sidewalk	Install accessible path		

City of White House Public Parks-Trails ADA Inventory

Park/Greenway/Parking/Sidewalks

Facility	Location	Observed Deficiency	Suggested Upgrade	Notes	Completion Date
White House Municipal Park	Parking #2 west side of Stadium Dr.	Accessible space not located near ramp or access area	Relocate close to entrances	Across Stadium Dr from Blue Play Area	
White House Municipal Park	Sidewalk between baseball fields 1-4 and blue play area	Sidewalk to baseball Field No. 1, Sand, dirt and gravel on path	keep path stable and firm-maintenance	also access to play area	
White House Municipal Park	Sidewalk between baseball fields 1-4 and blue play area	No accessible path to bleachers, playing fields	Need ADA design for Sports Facilities		
White House Municipal Park	Large parking lot east side of Stadium Dr.	2 accessible spaces near basketball court, not located near ramp	Relocate close to entrances		
White House Municipal Park	Basketball court and viewing area near Fields 1-4	Ramp to parking connects into parking space and not access aisle	Relocate accessible spaces to ramp location or, install new ramp at existing ADA location and repaint ramp location as no-parking area		
White House Municipal Park	Eastern parking ramp to restrooms	Running slope and cross slope exceed requirements	Consider replacing ramp		
White House Municipal Park	Fields 1-4 Concessions area	One picnic table not accessible	Replace table		
White House Municipal Park	Fields 1-4 Concessions area	Concessions window (42") exceeds height (38")	Lower counter		
White House Municipal Park	Paved area, bleachers and scorer's box Fields 1-4	Drain grate openings exceed 1/2 in.	replace grates		
White House Municipal Park	Paved area, bleachers and scorer's box Fields 1-4	Area around grates have slopes exceeding requirements	replace and regrade grate area		
White House Municipal Park	Paved area, bleachers and scorer's box Fields 1-4	Bleachers have no accessible ramp or viewing space	Need ADA design for Sports Facilities		
White House Municipal Park	Paved area, bleachers and scorer's box Fields 1-4	Bleachers have no optional ADA viewing area around bleachers	Need ADA design for Sports Facilities		
White House Municipal Park	Sidewalk to Field No. 7	Ramp down to field/bleachers has excessive slope and length	Consider redesign or alternate ADA path		
White House Municipal Park	Football Parking, West Side of Stadium Dr.	Need at least 5 additional accessible spaces and access	Reconfigure parking for required spaces		
White House Municipal Park	Football Parking, West Side of Stadium Dr.	Accessible space not located near ramp or access area	Include ramp access in new design		
White House Municipal Park	Parking near Fields Nos. 5 & 6	No accessible spaces	At least two accessible spaces should be added		
White House Municipal Park	Sidewalk to Fields Nos. 5 & 6	Excessive running & cross slopes	Consider redesigning/replacement of sidewalk		
White House Municipal Park	Sidewalk to Fields Nos. 5 & 6	No railing over ditch crossing	Consider redesigning/replacement of sidewalk		
White House Municipal Park	Sidewalk to Fields Nos. 5 & 6	No accessible path to bleachers, playing fields	Need ADA design for Sports Facilities		
White House Municipal Park	Sidewalk to Fields Nos. 5 & 6	Bleachers have no accessible ramp or viewing space	Need ADA design for Sports Facilities		
White House Municipal Park	Sidewalk to Fields Nos. 5 & 6	Bleachers have no optional ADA viewing area around bleachers	Need ADA design for Sports Facilities		

City of White House Public Parks-Trails ADA Inventory

Park/Greenway/Parking/Sidewalks

Facility	Location	Observed Deficiency	Suggested Upgrade	Notes	Completion Date
White House Municipal Park	Sidewalk from Greenway to Dog Park	Running slopes exceed 8.3% at drainage culvert	Regrade this segment to less than 8.3% slope		
White House Municipal Park	Dog Park Parking	Gravel Lot, No accessible spaces	At least two accessible spaces should be added		
White House Municipal Park	Dog Park Parking	No accessible access or paths inside Dog Park	Need ADA design for Sports Facilities		
White House Municipal Park	Parking Lot near Tennis/BBall Courts	No accessible path to bleachers	Need ADA design for Sports Facilities		
White House Municipal Park	Parking Lot near Tennis/BBall Courts	Bleachers have no accessible ramp or viewing space	Need ADA design for Sports Facilities		
White House Municipal Park	Parking Lot near Tennis/BBall Courts	Viewing benches should have back rests	Replace benches with compliant ones		

Section A-White House-ADA Sidewalk Inventory

West of I-65, North of SR 76

Street Name	Sidewalk Side	Start/End/Location	Length/Location	Deficiency Type	Deficiency Notes/Observations	Completion Date
East Winterberry Trail	Inner Loop	Willow Leaf Lane (S) to Willowleaf Lane (N)			Compliant	N/A
			#315,241,237,233,221,217,213 Driveways			
Foster Drive Loop	Inner Loop	Stop Sign at End of Loop; East	#407,411 Driveways	Discontinuity	Parallel expansion joint in path	#213, 217, 221 - 11/22/2023 #233, 237, 241, 315 - 12/15/2022
Foster Drive	East	Holly Lane to Foster Drive Loop	#106	Discontinuity	Parallel expansion joint in path	
Foster Drive Loop	Inner Loop	Stop Sign at End of Loop; East	Path from #305 and 315	Slope	Cross slope >2.0%	
Foster Drive Loop	Inner Loop	Stop Sign at End of Loop; East	Path from #305 and 315	Discontinuity	>1/4" change in level, sewer lid	
Foster Drive Loop	Inner Loop	Stop Sign at End of Loop; East	32' from Loop Intersection	Discontinuity	>1/4" change in level, sewer lid	
Holly Lane	South	Carrisa Circle to End of Path in Cul-de-Sac	#320,326,332 Driveways	Discontinuity	Parallel expansion joint in path	#308 Holly - 12/15/22
Holly Lane	South	Carrisa Circle to End of Path in Cul-de-Sac	18' past #316 Drive	Discontinuity	>1/4" change in level, cracked and broken	
Holly Lane	South	Carrisa Circle to End of Path in Cul-de-Sac	#310 Driveway	Discontinuity	>1/4" change in level, cracked and broken	
Holly Lane	South	Carrisa Circle to End of Path in Cul-de-Sac	#344	Obstruction	Tree in Path	
Holly Lane	South	Carrisa Circle to End of Path in Cul-de-Sac	932' of Path	Slope	Cross slope >2.0%	
Holly Lane	South	Foster Drive to Carrisa Circle	Multiple Discontinuities throughout path	Discontinuity	>1/4" change in level and broken or cracked path	
Holly Lane	South	104 Holly lane to Foster Drive	Near #112, 124, 138 on Path	Discontinuity	>1/4" change in level, cracked and broken	
Sundance Way	Outer Loop	Willow Leaf Lane to 100 Sundance Way	Entire Loop	Slope	Cross slope >2.0%	
Sundance Way	Outer Loop	Willow Leaf Lane to 100 Sundance Way	#100	Discontinuity	>1/4" change in level, sewer lid	
Sundance Way	Outer Loop	Willow Leaf Lane to 100 Sundance Way	#144	Discontinuity	>1/4" change in level, light pole base	
Sundance Way	Outer Loop	Willow Leaf Lane to 100 Sundance Way	#148,152,156,160,164, 172 Driveways	Driveway Slope	Cross slope >2.0%	
West Winterberry Trail	Inner Loop	Willow Leaf Lane (S) to Willowleaf Lane (N)	Entire Loop	Slope	Cross slope >2.0%	
Willowleaf Lane	West	Holly Lane to 111 Willowleaf Ln.	300' of path	Slope	Cross slope >2.0%	
Willowleaf Lane	West	Holly Lane to 111 Willowleaf Ln.	Near #101	Discontinuity	>1/4" change in level, water valve	
Willowleaf Lane	East	Savannah Court to Sundance Way	250' of path	Slope	Cross slope >2.0%	
Willowleaf Lane	East	140 Willowleaf Lane to Savannah Court	#134	Discontinuity	Parallel expansion joint in path	
Willowleaf Lane	East	140 Willowleaf Lane to Savannah Court	Near #134	Discontinuity	>1/4" change in level, light pole base	
Willowleaf Lane	East	Sundance Way to Winterberry Trail			Compliant	N/A
Willowleaf Lane	West	W Winterberry Trail to W Winterberry Trail	270' of path	Slope	Cross slope >2.0%	
Willowleaf Lane	East	E Winterberry Trail to E Winterberry Trail	270' of path	Slope	Cross slope >2.0%	

Section B-White House-ADA Sidewalk Inventory

East of I-65 to US 31W, North of SR 76

Street Name	Sidewalk Side	Start/End/Location	Length/Location	Deficiency Type	Deficiency Notes/Observations	Completion Date
Abbey Lane	South	101 Abbey Ln to 100 Abbey Ln	#101,103,107,109,111 Driveways	Ramp Slopes	Running slopes >5.0% both sides of each driveway	
Abbey Lane	South	101 Abbey Ln to 100 Abbey Ln	#101,103,107,109,111 Driveways	Ramp Slopes	Cross slope >2.0%	
Abbey Lane	South	101 Abbey Ln to 100 Abbey Ln	#101,103,107, 109, 111	Obstruction	Mailboxes mounted in path	
Apache Trail	North	Indian Ridge Blvd to Cherokee Drive (West)	Est. 160' of path	Slope	Cross slope >2.0%	
Apache Trail	North	Cherokee Drive (West) to Cherokee Drive (East)	12' before #804	Discontinuity	>1/4" change in level, square sewer lid	
Apache Trail	North	Cherokee Drive (West) to Cherokee Drive (East)	Est 715' of path	Width	Handicap 5 x 5 passing spaces not provided every 200' (SW width <5.0')	
Apache Trail	North	Cherokee Drive (West) to Cherokee Drive (East)	#802,800, Driveways	Discontinuity	Parallel expansion joint in path	
Apache Trail	North	Cherokee Drive (East) to Mohawk Court	Est 255' of path	Width	Handicap 5 x 5 passing spaces not provided every 200' (SW width <5.0')	
Apache Trail	North	Cherokee Drive (East) to Mohawk Court	Est 255' of path	Slope	Cross slope >2.0%	
Apache Trail	North	Cherokee Drive (East) to Mohawk Court	#603,605 Driveways	Discontinuity	>1/4" change in level Either side of driveway	
Apache Trail	North	Mohawk Court to Algonquin Court	Est 220' of path	Width	Handicap 5 x 5 passing spaces not provided every 200' (SW width <5.0')	
Apache Trail	North	Algonquin Court to N. Aztec Dr.	Est 415' of path	Width	Handicap 5 x 5 passing spaces not provided every 200' (SW width <5.0')	
Apache Trail	North	Algonquin Court to N. Aztec Dr.	Est 415' of path	Slope	Cross slope >2.0%	
Apache Trail	North	Algonquin Court to N. Aztec Dr.	Besides Chain Link Fence, & near #309	Discontinuity	>1/4" change in level and broken or cracked path	
Apache Trail	North	Algonquin Court to N. Aztec Dr.	#309 Driveway	Ramp Slope	Running slopes >5.0% both sides of each driveway	
Apache Trail	North	N. Aztec Dr. to Choctaw Court	Est 820' of path	Width	Handicap 5 x 5 passing spaces not provided every 200' (SW width <5.0')	
Apache Trail	North	N. Aztec Dr. to Choctaw Court	Est 820' of path	Slope	Cross slope >2.0%	
Apache Trail	North	N. Aztec Dr. to Choctaw Court	Before #213 driveway	Discontinuity	>1/4" change in level and broken or cracked path	
Apache Trail	North	N. Aztec Dr. to Choctaw Court	After #213 driveway	Obstruction	Holly Bush overgrowth	
Apache Trail	North	N. Aztec Dr. to Choctaw Court	Chain Link Fence/Culvert Crossing	Discontinuity	>1/4" change in level and broken or cracked path	
Apache Trail	North	N. Aztec Dr. to Choctaw Court	#309, 207, 205, 203 Driveways	Discontinuity	>1/4" change in level Either side of driveway	
Apache Trail	North	Choctaw Court to Calista Road	Est 235' of path	Width	Handicap 5 x 5 passing spaces not provided every 200' (SW width <5.0')	
Apache Trail	North	Choctaw Court to Calista Road	Before end of path near Calista Road	Discontinuity	>1/4" change in level and broken or cracked path	
Calista Road	South	Indian Ridge Blvd to Indian Ridge Village Entrance			Compliant	
Charles Drive	West	HWY 76 to McDonalds Entrance			Compliant	
Cheyenne Drive	North	Indian Ridge Blvd to Barksdale	Est 900' of path	Slope	Cross slope >2.0%	
Cheyenne Drive	North	Indian Ridge Blvd to Barksdale	#100,106,204,208,212 Driveways	Ramp Slopes	Cross slope >2.0%	
Cheyenne Drive	North	Indian Ridge Blvd to Barksdale	#106	Discontinuity	>1/4" change in level, water valve	
Cottage Trace Drive	North/South	1001 Cottage Trace to 100 Cottage Trace			Compliant	
Indian Ride Circle	Outer Loop	Indian Ridge Circle Loop	Entire Loop	Slope	Cross slope >2.0%	
Indian Ride Circle	Outer Loop	Indian Ridge Circle Loop	Two 5-space Parallel Street Parking	Handicap Access	Aisle/Ramp not provided	
Indian Ridge Blvd.	West	Stadium Drive to Lone Oak Dr.	Est. 683' of path	Slope	Cross slope >2.0%	
Indian Ridge Blvd.	West	Stadium Drive to Lone Oak Dr.	Est. 683' of path	Slope	Cross slope >2.0%	
Indian Ridge Blvd.	West	Stadium Drive to Lone Oak Dr.	#2973,2977,2985,2989,2993 Driveways	Driveway Slope	Cross slope >2.0%	
Indian Ridge Blvd.	West	Stadium Drive to Lone Oak Dr.	Past #2993	Discontinuity	>1/4" change in level, water valve	
Indian Ridge Blvd.	West	Lone Oak Drive to Wyoming Drive	378' of path	Width	Handicap 5 x 5 passing spaces not provided every 200' (SW width <5.0')	
Indian Ridge Blvd.	West	Lone Oak Drive to Wyoming Drive	#3001	Discontinuity	>1/4" change in level, Multiple sewer and wter valve boxes in path	
Indian Ridge Blvd.	West	Lone Oak Drive to Wyoming Drive	#3009	Obstruction	Mailbox mounted in path	
Indian Ridge Blvd.	West	Lone Oak Drive to Wyoming Drive	#4005	Discontinuity	>1/4" change in level, broken and cracked driveway	
Indian Ridge Blvd.	West	Wyoming Drive to Cheyenne Drive	Est 750' of path	Width	Handicap 5 x 5 passing spaces not provided every 200' (SW width <5.0')	
Indian Ridge Blvd.	West	Wyoming Drive to Cheyenne Drive	#6001,6005,6011,6017,6023 Driveways	Driveway Slope	Cross slope >2.0%	
Indian Ridge Blvd.	West	Wyoming Drive to Cheyenne Drive	Path between #6011-6017	Firm & Stable	Loose gravel, grass overgrowth	
Indian Ridge Blvd.	West	Cheyenne Drive to Iroquois Drive	Est. 590' of path	Width	Handicap 5 x 5 passing spaces not provided every 200' (SW width <5.0')	
Indian Ridge Blvd.	West	Cheyenne Drive to Iroquois Drive	#7007,7011,7017,7019 Driveways	Driveway Slope	Cross slope >2.0%	

Section B-White House-ADA Sidewalk Inventory

East of I-65 to US 31W, North of SR 76

Street Name	Sidewalk Side	Start/End/Location	Length/Location	Deficiency Type	Deficiency Notes/Observations	Completion Date
Indian Ridge Blvd.	West	Cheyenne Drive to Iroquois Drive	#7011 Driveway	Discontinuity	>1/4" change in level, broken and cracked driveway	
Indian Ridge Blvd.	West	Iroquois Drive to Calista Road	Est. 300' of path	Width	Handicap 5 x 5 passing spaces not provided every 200' (SW width <5.0')	
Indian Ridge Blvd.	West	Iroquois Drive to Calista Road	#7026 & 8006 Driveways	Discontinuity	Parallel expansion joint in path	
Indian Ridge Blvd.	West	Iroquois Drive to Calista Road	Est. 300' of path	Slope	Cross slope >2.0%	
Indian Ridge Circle	Outer Loop	Indian Ridge Circle Loop	Multiple Driveways	Driveway Slope	Cross slope >2.0%	
Indian Ridge Village	West/East	Calista Road Entrance to Indian Ridge Circle	Est. 170' (2) of path	Slope	Cross slope >2.0%	
Laurelwood Drive	North/South	Laurelwood Drive			Compliant	
Lone Oak Drive	West to North	219 Lone Oak Dr. to Indian Ridge Blvd.	Est. 1000' of path	Slope	Cross slope >2.0%	
Lone Oak Drive	West to North	219 Lone Oak Dr. to Indian Ridge Blvd.	#233	Discontinuity	>1/4" change in level, manhole cover	
Lone Oak Drive	West to North	219 Lone Oak Dr. to Indian Ridge Blvd.	#325	Obstruction	Bushes, Mailbox mounted in path	
Lone Oak Drive	West to North	219 Lone Oak Dr. to Indian Ridge Blvd.	Multiple Discontinuities throughout path	Discontinuity	>1/4" change in level and broken or cracked path	
Richard Wilks Road	South	Wilkinson Lane to Burger King Entrance			Compliant	
Stadium Drive	North	Lone Oak Drive to Indian Ridge Blvd.	Path between #300 & 304	Slope	Cross slope >2.0%	
Stadium Drive	North	Lone Oak Drive to Indian Ridge Blvd.	#308,304 Driveways	Driveway Slope	Running slopes >5.0% both sides of each driveway	
Stadium Drive	North	Indian Ridge Blvd. to Gate of Park	#2968	Ramp Slopes	Cross slope >2.0%	
Stadium Drive	North	Indian Ridge Blvd. to Gate of Park	#2968	Ramp Slopes	Running slopes >5.0% both sides of each driveway	
Village Park Drive	West/East	Village Park Drive, both sides	Est. 270' of path	Slope	Cross slope >2.0%	
Village Park Drive	West/East	Village Park Drive, both sides	101-107 Village Park Drive Parking	Handicap Access	Aisle/Ramp not provided	
Wilkinson Lane	West	Richard Wilks Road to HWY 76	Multiple Discontinuities throughout path	Discontinuity	>1/4" change in level and broken or cracked path	
Wilkinson Lane	West	Richard Wilks Road to HWY 76	Power Pole in Path near Dollar Tree	Obstruction	Utility Pole in Path	
Wilkinson Lane	West	Richard Wilks Road to Walmart Entrance/Murphy USA	Est. 375' of path	Slope	Cross slope >2.0%	
Wilkinson Lane	West	Walmart Entrance/Murphy USA to before Edenway Dr.	Est 428' of path	Slope	Cross slope >2.0%	
Wilkinson Lane	West	Walmart Entrance/Murphy USA to before Edenway Dr.	Multiple Discontinuities throughout path	Discontinuity	>1/4" change in level and broken or cracked path	
Wilkinson Lane	West	Walmart Entrance/Murphy USA to before Edenway Dr.	Ramp at end of segment	Ramp Slope	Running slopes >5.0%	

Section C-White House-ADA Sidewalk Inventory

East of I-65 to US 31W, South of SR 76

Street Name	Sidewalk Side	Start/End/Location	Length/Location	Deficiency Type	Deficiency Notes/Observations	Completion Date
Blossom Court	North	Magnolia Blvd. through Blossom Court Cul-de-Sac	#102,208,212,209 Driveways	Driveway Slope	Cross slope >2.0%	
Blossom Court	North	Magnolia Blvd. through Blossom Court Cul-de-Sac	Path between 209 & 211, and before Tulip	Discontinuities	>1/4" of path	
Blueberry Street	Inner Loop	Blueberry (S) to Blueberry (N) & Cherry Lane	Est 1754' of path	Width	Handicap 5 x 5 passing spaces not provided every 200' (SW width <5.0')	
Blueberry Street	Inner Loop	Blueberry (S) to Blueberry (N) & Cherry Lane	#173,181,213,189	Obstruction	Mailbox in Path	
Blueberry Street	Inner Loop	Blueberry (S) to Blueberry (N) & Cherry Lane	#173,177,181,189,193,197,201,205 Driveways	Driveway Slope	Cross slope >2.0%	
Blueberry Street	Inner Loop	Blueberry (S) to Blueberry (N) & Cherry Lane	Est 1754' of path	Slope	Cross slope >2.0%	
Blueberry Street	Inner Loop	Blueberry (S) to Blueberry (N) & Cherry Lane	Path between 173 & 177	Discontinuities	>1/4" of path, Cracked & Broken	
Blueberry Street	Inner Loop	Blueberry (S) to Blueberry (N) & Cherry Lane	#177 Both sides of Driveway	Discontinuities	>1/4" of path, Cracked & Broken	
Blueberry Street	Inner Loop	Blueberry (S) to Blueberry (N) & Cherry Lane	Path between #181-185	Slope	Running slope >5.0%	
Blueberry Street	Inner Loop	Blueberry (S) to Blueberry (N) & Cherry Lane	#193 ramp to driveway	Slope	Running slope >5.0%	
Blueberry Street	Inner Loop	Blueberry (S) to Blueberry (N) & Cherry Lane	#213 both sides of Driveway	Discontinuities	>1/4" of path, Cracked & Broken	
Blueberry Street	Inner Loop	Blueberry (S) to Blueberry (N) & Cherry Lane	End of Path @ Cherry Lane	Discontinuity	>1/4" of path, Gas Valve	
Business Park Drive	North/South	HWY 31W to Cul-de-Sac	Ramp by fire hydrant, Fire Dept Drive	Discontinuity	>1/4" of path, Water, Gas Valve, slope	
Business Park Drive	North/South	HWY 31W to Cul-de-Sac	Past Fire Dept Drive	Discontinuity	>1/4" of path, gas valves	
Business Park Drive	North/South	HWY 31W to Cul-de-Sac	Perpendicular Curb Ramps at 31W	Detectable Warning	Not present, slopes and discontinuities	
Business Park Drive	North/South	HWY 31W to Cul-de-Sac	Path on South Side	Firm & Stable	Lots not developed, mud, grass, tree limbs	
Business Park Drive	North/South	HWY 31W to Cul-de-Sac	Parallel Curb Ramp, South side end of Path	Detectable Warning	Not present, slopes and discontinuities	
Cherry Lane	East	318 Cherry Ln. to Sage Road	#318	Obstruction	Tree Limbs	
Cherry Lane	East	318 Cherry Ln. to Sage Road	Est 2006' of path	Width	Handicap 5 x 5 passing spaces not provided every 200' (SW width <5.0')	
Cherry Lane	East	318 Cherry Ln. to Sage Road	Est 2006' of path	Slope	Cross slope >2.0%	
Cherry Lane	East	318 Cherry Ln. to Sage Road	#312,306,212,208,198,194,190 Driveways	Driveway Slope	Cross slope >2.0%	
Cherry Lane	East	318 Cherry Ln. to Sage Road	Multiple Discontinuities throughout path	Discontinuity	>1/4" of path and broken or cracked path	
Cherry Lane	East	318 Cherry Ln. to Sage Road	#204 Mailbox	Discontinuity	Mailbox concrete cutout in path	
Dorchester Drive	South	204 Dorchester to Williamsburg Drive	Est 735' of path	Width	Handicap 5 x 5 passing spaces not provided every 200' (SW width <5.0')	
Dorchester Drive	South	204 Dorchester to Williamsburg Drive	Parallel Curb Ramp at Start of Sidewalk	Detectable Warning	Not present, slopes	
Dorchester Drive	South	204 Dorchester to Williamsburg Drive	#204,202,200,108,106,104,102 Driveways	Driveway Slope	Cross slope >2.0%	
Dorchester Drive	South	204 Dorchester to Williamsburg Drive	Parallel Curb Ramp at piccadilly Dr.	Detectable Warning	Not present, slopes	
Gem Court	North	126 Gem to Magnolia Blvd.	#126 Driveway	Discontinuity	>1/4" of path Either side of driveway	
Gem Court	North	126 Gem to Magnolia Blvd.	#120 Driveway	Ramp Slopes	Running slopes >5.0% both sides of each driveway	
Gem Court	North	126 Gem to Magnolia Blvd.	#108,102 Driveways	Driveway Slope	Cross slope >2.0%	
Granda Flora Drive	South	Union Road to Magnolia Blvd.	55' past #100 & 75' past 204 driveways	Discontinuity	>1/4" of path and broken or cracked path	
Hester Drive	South	Hampton Inn to HWY 76	Hampton Inn	Obstruction	Bush overgrowth in path	
Hester Drive	South	Hampton Inn to HWY 76	Before Cracker Barrell Drive	Slope	Running slope >5.0%	
Hester Drive	South	Hampton Inn to HWY 76	Between Quality Inn Drives	Slope	Cross slope >2.0%	
Hester Drive	South	Hampton Inn to HWY 76	Across Knight Circle	Discontinuity	>1/4" of path, storm grate has separated from sidewalk	
Hester Drive	South	Hampton Inn to HWY 76	Past Motel 6	Discontinuity	Mailbox post cutout in path	
Hester Drive	South	Hampton Inn to HWY 76	Past Motel 6	Guardrail	No middle rail	
Hester Drive	South-East	Hampton Inn to HWY 76	Taco Bell	Obstruction	Mailbox in Path	
Hester Drive	West	Hardee's to HWY 76	Entire Segment	Discontinuities	>1/4" of path and broken or cracked path	
Knight Circle	West	Hester Drive to Past Maiden Lane	Multiple Discontinuities throughout path	Discontinuity	>1/4" of path and broken or cracked path	
Knight Circle	West	Hester Drive to Past Maiden Lane	Parallel Curb Ramps at Holiday Inn Express	Detectable Warning	Not compliant, slopes exceed, no perpendicular grade	
Knight Circle	West	Hester Drive to Past Maiden Lane	Path between Holiday Inn Drives	Discontinuity	>1/4" of path and broken or cracked path	
Madeline Way	East/West	Crossroads Medical Plaza Entrance to N. Sage Road	85' & 115' from start of Path	Discontinuity	>1/4" of path and broken or cracked path	
Madeline Way	East	Crossroads Medical Plaza Entrance to N. Sage Road	Parallel Curb Ramps at Entrance to Crossroads	Detectable Warning	Not compliant, slopes exceed, no perpendicular grade, turning space	
Madeline Way	East	Crossroads Medical Plaza Entrance to N. Sage Road	Parallel Curb Ramps at Entrance to Standard Apt	Detectable Warning	Not compliant, slopes exceed, no perpendicular grade, turning space	

Section C-White House-ADA Sidewalk Inventory

East of I-65 to US 31W, South of SR 76

Street Name	Sidewalk Side	Start/End/Location	Length/Location	Deficiency Type	Deficiency Notes/Observations	Completion Date
Madeline Way	West	Crossroads Medical Plaza Entrance to N. Sage Road	Multiple Discontinuities throughout path	Discontinuity	>1/4" of path and broken or cracked path, missing sections	
Magnolia Blvd.	West	125 Magnolia Blvd. to Blossom Ct.	#141,157,301, Driveways	Driveway Slope	Cross slope >2.0%	
Magnolia Blvd.	West	125 Magnolia Blvd. to Blossom Ct.	Path between 125 & 129/133 & 137	Discontinuity	>1/4" of path settled	
Magnolia Blvd.	West	125 Magnolia Blvd. to Blossom Ct.	Parallel Curb Ramps at Gem Ct.	Ramp	Not compliant, turning space, slopes	
Maiden Lane	South	Knight Circle to N. Sage Road	Completed Segments	Slope	Cross slope >2.0%	
Peachtree Street	West	209 Peachtree St to Blueberry St.	Est 750'	Width	Handicap 5 x 5 passing spaces not provided every 200' (SW width <5.0')	
Peachtree Street	West	209 Peachtree St to Blueberry St.	#209,213,217,221,225,231, Driveways	Driveway Slope	Cross slope >2.0%	
Peachtree Street	West	209 Peachtree St to Blueberry St.	#213 mailbox & at Blueberry St	Obstruction	Tree limbs in path	
Peachtree Street	West	209 Peachtree St to Blueberry St.	#217	Obstruction	Hanging on back of mailbox limiting path	
piccadilly Drive	West	Westchester Drive to Chesire Drive	Est 750' of path	Width	Handicap 5 x 5 passing spaces not provided every 200' (SW width <5.0')	
piccadilly Drive	West	Westchester Drive to Chesire Drive	Dorchester Road (south side)	Ramp	No Ramp	
piccadilly Drive	West	Westchester Drive to Chesire Drive	#885,891 Driveways	Driveway Slope	Cross slope >2.0%	
piccadilly Drive	West	Westchester Drive to Chesire Drive	Dorchester Road (north side)	Ramp	Not compliant, turning space, slopes, no detectable warning	
Pierre Place	North	142 Pierre Place to Magnolia Blvd.	#151, 131, 111 Driveways	Driveway Slope	Cross slope >2.0%	
Pierre Place	North	142 Pierre Place to Magnolia Blvd.	15' past #121 driveway	Discontinuity	>1/4" of path, water meter	
Pierre Place	North	142 Pierre Place to Magnolia Blvd.	Est 880' of path	Slope	Cross slope >2.0%	
Raymond Hirsch Pkwy	West	HWY 76 to Speedway Gas Entrance			Compliant	
N. Sage Road	West	Madeline Way to HWY 76	Est 1210' of path	Width	Handicap 5 x 5 passing spaces not provided every 200' (SW width <5.0')	
N. Sage Road	West	Madeline Way to HWY 76	Est 1210' of path	Slope	Cross slope >2.0%	
Southern Terrace	North	142 Southern Terrace to Magnolia Blvd.	#129, 125,121,111,103 Driveways	Driveway Slope	Cross slope >2.0%	
Southern Terrace	North	142 Southern Terrace to Magnolia Blvd.	#143,139,135 Driveways	Ramp Slopes	Cross slope >2.0%	
Southern Terrace	North	142 Southern Terrace to Magnolia Blvd.	#143,139,135 Driveways	Ramp Slopes	Running slopes >5.0% both sides of each driveway	
Southern Terrace	North	142 Southern Terrace to Magnolia Blvd.	End of Path @ Magnolia	Firm & Stable	Mud, slippery	
Star Place	North	140 Star Place to Magnolia Blvd.	#144 driveway	Discontinuity	>1/4" of path, sewer cover	
Tulip Terrace	West	Blossom Ct. to Grande Flora Dr.			Compliant	
Westchester Drive	North	Williamsburg Drive to End of Dr.	Est 650' of path	Width	Handicap 5 x 5 passing spaces not provided every 200' (SW width <5.0')	
Westchester Drive	North	Williamsburg Drive to End of Dr.	Near #101	Discontinuity	>1/4" of path, near underground transformer	
Westchester Drive	North	Williamsburg Drive to End of Dr.	Near #111 driveway	Discontinuity	>1/4" of path and broken or cracked path	
Westchester Drive	North	Williamsburg Drive to End of Dr.	#113, 203 Driveways	Driveway Slope	Cross slope >2.0%	
Westchester Drive	North	Williamsburg Drive to End of Dr.	Parallel Curb Ramp at end of route	Ramp	Not compliant, turning space, slopes, no detectable warning	
Williamsburg Drive	East	207 Williamsburg Dr. to Gazebo neat Westchester Dr.	Est 600' of path	Width	Handicap 5 x 5 passing spaces not provided every 200' (SW width <5.0')	

Section D-White House-ADA Sidewalk Inventory

East of US 31W, North of SR 76

Street Name	Sidewalk Side	Start/End/Location	Length/Location	Deficiency Type	Deficiency Notes/Observations	Completion Date
Briarwood Drive	North	406 Cassandra Dr. to HWY 31W	#406 Cassandra Dr.	Discontinuity	>1/4" of path, Mailbox foundation in path	
Briarwood Drive	North	406 Cassandra Dr. to HWY 31W	Est 1400' of path	Slope	Cross slope >2.0%	
Briarwood Drive	North	406 Cassandra Dr. to HWY 31W	Multiple Driveways	Discontinuity	>1/4" of path Either side of driveway	
Briarwood Drive	North	406 Cassandra Dr. to HWY 31W	# 1051, 1043, 1039, 1035, 1021, 1013, 1007 Driveways	Driveway Slope	Cross slope >2.0%	
Cassandra Drive	East	Cassandra Dr. (Denise Circle) to 221 Cassandra Dr.	#101 & 105 Driveways	Discontinuity	>1/4" of path Either side of driveway	
Cassandra Drive	East	Cassandra Dr. (Denise Circle) to 221 Cassandra Dr.	#101 & 105 Driveways	Discontinuity	>1/4" of path Either side of driveway	
Cassandra Drive	East	Cassandra Dr. (Denise Circle) to 221 Cassandra Dr.	# 101, 105 Driveways	Driveway Slope	Cross slope >2.0%	
Christian Drive	North	301 Christian Dr. to 433 Christian Drive	Est 910' of path	Width	Handicap 5 x 5 passing spaces not provided every 200' (SW width <5.0')	
Christian Drive	North	301 Christian Dr. to 433 Christian Drive	#309, 433, Christian Dr.	Discontinuity	>1/4" of path, Mailbox foundation in path	
Christian Drive	North	301 Christian Dr. to 433 Christian Drive	Multiple Mailboxes	Discontinuity	>1/4" of path, Grass growth between sidewalk and added concrete	
Christian Drive	North	301 Christian Dr. to 433 Christian Drive	Est 910' of path	Slope	Cross slope >2.0%	
Christian Drive	North	301 Christian Dr. to 433 Christian Drive	Multiple Driveways	Driveway Slope	Cross slope >2.0%	
Christian Drive	North	301 Christian Dr. to 433 Christian Drive	Path between #309 & 313	Discontinuity	>1/4" of path broken and cracked	
Christian Drive	North	301 Christian Dr. to 433 Christian Drive	At Lauren Drive	Ramp	No Ramps, no detectable warnings either side	
Christian Drive	North	301 Christian Dr. to 433 Christian Drive	Past #309	Discontinuity	>1/4" of path broken and cracked, curb separated from sidewalk	
Denise Circle	Outer Loop	402 Denise Circle to 202 Denise Circle			Compliant	
Lauren Drive	Inner Loop	137 Lauren Drive to Christian Drive	Est 2100' of path	Width	Handicap 5 x 5 passing spaces not provided every 200' (SW width <5.0')	
Lauren Drive	Inner Loop	137 Lauren Drive to Christian Drive	Est 2100' of path	Slope	Cross slope >2.0%	
Lauren Drive	Inner Loop	137 Lauren Drive to Christian Drive	#137,129,125 Driveways	Driveway Slope	Cross slope >2.0%	
Lauren Drive	Inner Loop	137 Lauren Drive to Christian Drive	Near #152 in Path	Discontinuity	>1/4" of path broken and cracked, large sewer manway	
Lauren Drive	Inner Loop	137 Lauren Drive to Christian Drive	Three street storm drains	Discontinuity	>1/4" of path broken and cracked, Sidewalk has settled	
Oakland Court	North	113 Oakland (HWY 31W) to Carson Ct.	Est 420' of path	Width	Handicap 5 x 5 passing spaces not provided every 200' (SW width <5.0')	
Oakland Court	North	113 Oakland (HWY 31W) to Carson Ct.	Est 420' of path	Slope	Cross slope >2.0%	
Oakland Court	North	113 Oakland (HWY 31W) to Carson Ct.	Ramp at Carson Ct.	Ramp	Detectable Warning does not extend width, no turning space, slopes	
Reidway Drive	West	104 Reidway Dr. to Christian Dr.	Est 740' of path	Width	Handicap 5 x 5 passing spaces not provided every 200' (SW width <5.0')	
Reidway Drive	West	104 Reidway Dr. to Christian Dr.	At Ashley Drive	Ramp	No Ramps, no detectable warnings either side	
Reidway Drive	West	104 Reidway Dr. to Christian Dr.	#108,112, Driveways	Discontinuity	>1/4" of path Either side of driveway	
Reidway Drive	West	104 Reidway Dr. to Christian Dr.	#104 Driveway	Driveway Slope	Cross slope >2.0%	
Renee Court	South	206 Renee Court to Cassandra Drive	Past #207	Discontinuity	Sidewalk segment missing, graveled for new construction entrance	

Section E-White House-ADA Sidewalk Inventory

East of US 31W, South of SR 76

Street Name	Sidewalk Side	Start/End/Location	Length/Location	Deficiency Type	Deficiency Notes/Observations	Completion Date
Allers Drive	West	109 Allen Drive to Adtsea Drive	314' of path	Slope	Cross slope >2.0% , entire segment	
Allers Drive	West	109 Allen Drive to Adtsea Drive	#107, 109 Driveways	Driveway Slope	Cross slope >2.0%	
Amber Lane	South	305 Amber Ln. to Fieldstone Dr.	#301,205,105 Driveways	Driveway Slope	Cross slope >2.0%	
Amber Lane	South	305 Amber Ln. to Fieldstone Dr.	# 205	Obstruction	Overgrown bush blocking path	
Artesa Drive	North	425 Artdea Dr. to McCurdy Dr.	#303, Driveways	Driveway Slope	Running slopes >5.0% both sides of each driveway	
Artesa Drive	North	425 Artdea Dr. to McCurdy Dr.	#421,401,307,303,200,111, 101 Driveways	Driveway Slope	Cross slope >2.0%	
Artesa Drive	North	425 Artdea Dr. to McCurdy Dr.	Path between #307 & 303	Discontinuity	Broken Concrete	
Artesa Drive	North	425 Artdea Dr. to McCurdy Dr.	perpendicular Curb Ramps at Firestone	Detectable Warning Surface	Not present, slopes and discontinuities	
Artesa Drive	North	425 Artdea Dr. to McCurdy Dr.	perpendicular Curb Ramps at etude	Detectable Warning Surface	Not present, slopes and discontinuities	
Baylee Court	East	121 Baylee to S Palmers Chapel Road	#101, 105 109 Driveways	Driveway Slope	Cross slope >2.0%	
Baylee Court	East	121 Baylee to S Palmers Chapel Road	#101, 105 109 Driveways	Discontinuity	Parallel expansion joint in path	
Baylee Court	East	121 Baylee to S Palmers Chapel Road	perpendicular Curb Ramp at S Palmers	Detectable Warning Surface	Not present	
Bedrock Drive	East	402 Bedrock to Amber Lane	#402,300,222,218,212,208,108	Driveway Slope	Running slopes >5.0% both sides of each driveway	
Bedrock Drive	East	402 Bedrock to Amber Lane	#402,300,222,218,212,208,108	Driveway Slope	Cross slope >2.0%	
Bedrock Drive	East	402 Bedrock to Amber Lane	Across from Cobblestone Dr.	Discontinuity	Sewer Lid in path	
Brigham Court	North-NE	124 Brigham Ct. to Chapman Drive	Path between #104 & 114	Discontinuity	>1/4" change of level	
Brigham Court	North-NE	124 Brigham Ct. to Chapman Drive	#114 Driveway	Discontinuity	Parallel expansion joint in path	
Cambrea Drive	South	McCurdy Road through Roundabout	#100, 104, 108, 112, 116 Driveways	Driveway Slope	Cross slope >2.0%	
Chandler Blvd.	West	119 Chandler Blvd to 245 Chandler Blvd	#123,201,209,237 Driveway	Discontinuity	Parallel expansion joint in path	
Chandler Blvd.	West	119 Chandler Blvd to 245 Chandler Blvd	Multiple Driveways	Driveway Slope	Cross slope >2.0%	
Chapman Drive	West	213 Chapman Dr. to N. Plamers Chapel Road	#213,203 Driveways	Driveway Slope	Cross slope >2.0%	
Chapman Drive	West	213 Chapman Dr. to N. Plamers Chapel Road	#Path fronting 213,203	Obstruction	Overhanging bushes blocks path	
Chapman Drive	West	213 Chapman Dr. to N. Plamers Chapel Road	perpendicular Curb Ramp at Clarice	Detectable Warning Surface	Not present	
Clarice Court	East	113 Clarice Ct. to Morgan Trace Ct.	#101, 105 109 Driveways	Driveway Slope	Cross slope >2.0%	
Clarice Court	East	113 Clarice Ct. to Morgan Trace Ct.	#109 Driveway	Ramp Slopes	Running slopes >5.0% both sides of each driveway	
Clarice Court	East	113 Clarice Ct. to Morgan Trace Ct.	#109 Driveway	Discontinuity	Parallel expansion joint in path	
cliff Garrett Dr.	South	138 cliff Garrett Dr. to HWY 31W	Est 224' of path	Slope	Cross slope >2.0%	
cliff Garrett Dr.	South	138 cliff Garrett Dr. to HWY 31W	Break in Path from #138 to 120	Firm, Stable	No sidewalk between segments	
Cobblestone Court	North	112 Cobblestone to Bedrock Dr.	Path from #108 to end of segment	Slope	Cross slope >2.0%	
Cobblestone Court	North	112 Cobblestone to Bedrock Dr.	#102, 108, 112 Driveways	Driveway Slope	Running slopes >5.0% both sides of each driveway	
Cobblestone Court	North	112 Cobblestone to Bedrock Dr.	#102, 108, 112 Driveways	Driveway Slope	Cross slope >2.0%	
Cobblestone Court	North	112 Cobblestone to Bedrock Dr.	perpendicular Curb Ramp at Bedrock	Detectable Warning Surface	Not present, slopes and discontinuities	
Crystal Court	Outer Circle	101 Crystal Ct. to Bedrock Dr.	perpendicular Curb Ramp at Bedrock	Detectable Warning Surface	Not present, slopes and discontinuities	
Cuvee Court	Outer Circle	101 Cuvee Ct. to Artesa Drive			Compliant	
Danbury Court	South	111 Danbury Ct. to 103 Danbury Ct.	Stop Sign at Chapman	Obstruction	Stop Sign obstructs path	
Etude Court	Outer Circle	106 Etude Ct. to Artesa Drive	#103 Etude Section	Discontinuity	>1/4" change of level, Water Meter	
Fieldstone Drive	West	100 Fieldstone Dr. to Sapphire Dr.	#205, 407, 423 Driveways	Driveway Slope	Cross slope >2.0%	
Fieldstone Drive	West	100 Fieldstone Dr. to Sapphire Dr.	#209	Obstruction	Mailbox and overgrown bush obstruct path	
Fieldstone Drive	West	100 Fieldstone Dr. to Sapphire Dr.	#209	Obstruction	Mailbox and overgrown bush obstruct path	
Fieldstone Drive	West	100 Fieldstone Dr. to Sapphire Dr.	perpendicular Curb Ramp at Amber	Detectable Warning Surface	Not present, slopes and discontinuities	
Firestede Court	Outer Circle	109 Firestede Ct. to Artesa Drive	Entire Segment	Slope	Cross slope >2.0%	
Firestede Court	Outer Circle	109 Firestede Ct. to Artesa Drive	#105 Driveway	Discontinuity	>1/4" change of level Either side of driveway	
Granite Court	West & Circle	106 Granite Ct.			Compliant, Only house on Court	
Grayson Lane	East	133 Grayson Ln to Thoroughbred Way	#109,113,117,121,127,133 Driveways	Driveway Slope	Cross slope >2.0%	
Highland Drive	South	Laura Drive to 901 Highland Dr.	Est 2460' of path	Width	Entire length <4.0'	
Highland Drive	South	Laura Drive to 901 Highland Dr.	#301 , 303	Obstruction	Overgrown bush blocking path	
Highland Drive	South	Laura Drive to 901 Highland Dr.	Parallel Curb Ramps at Belle Reve	Detectable Warning Surface	Not present, slopes and discontinuities	
Highland Drive	South	Laura Drive to 901 Highland Dr.	Parallel Curb Ramps at Indian Point Dr.	Detectable Warning Surface	Not present, slopes and discontinuities	
Highland Drive	South	Laura Drive to 901 Highland Dr.	Parallel Curb Ramps at Northwood Dr.	Detectable Warning Surface	Not present, slopes and discontinuities	
Highland Drive	South	Laura Drive to 901 Highland Dr.	Path from Northwood to Sycamore	Slope	Running slope >5.0%	
Highland Drive	South	Laura Drive to 901 Highland Dr.	Parallel Curb Ramps at Hunterwood Dr.	Detectable Warning Surface	Not present, slopes and discontinuities	

Section E-White House-ADA Sidewalk Inventory

East of US 31W, South of SR 76

Street Name	Sidewalk Side	Start/End/Location	Length/Location	Deficiency Type	Deficiency Notes/Observations	Completion Date
Highland Drive	South	Laura Drive to 901 Highland Dr.	#809	Obstruction	Overgrown tree blocking path	
Honeysuckle Drive	South	185 Honeysuckle to Sycamore Dr.	Est 2770'	Width	Handicap 5 x 5 passing spaces not provided every 200' (SW width <5.0')	
Honeysuckle Drive	South	185 Honeysuckle to Sycamore Dr.	Multiple Driveways	Driveway Slope	Cross slope >2.0%	
Honeysuckle Drive	South	185 Honeysuckle to Sycamore Dr.	Multiple Driveways	Discontinuity	>1/4" change of level Either side of driveway	
Honeysuckle Drive	South	185 Honeysuckle to Sycamore Dr.	Multiple Driveways	Discontinuity	Parallel expansion joint in path	
Honeysuckle Drive	South	185 Honeysuckle to Sycamore Dr.	#153	Obstruction	Overgrown tree blocking path	
Hunterwood Drive	West	101 Hunterwood Dr. to Magnolia Drive	Est 1935' of path	Width	Handicap 5 x 5 passing spaces not provided every 200' (SW width <5.0')	
Hunterwood Drive	West	101 Hunterwood Dr. to Magnolia Drive	Multiple discontinuities throughout path	Discontinuity	>1/4" change of level and broken or cracked path	
Hunterwood Drive	West	101 Hunterwood Dr. to Magnolia Drive	#203, 305, 407	Obstruction	Overgrown trees blocking path	
Hunterwood Drive	West	101 Hunterwood Dr. to Magnolia Drive	Parallel Curb Ramps at Cypress Ct.	Detectable Warning Surface	Not present, slopes and discontinuities	
Hunterwood Drive	West	101 Hunterwood Dr. to Magnolia Drive	Parallel Curb Ramps at Pinewood Dr.	Detectable Warning Surface	Not present, slopes and discontinuities	
Hunterwood Drive	West	101 Hunterwood Dr. to Magnolia Drive	Parallel Curb Ramps at Magnolia Dr.	Detectable Warning Surface	Not present, slopes and discontinuities	
Landons Circle	Outer Circle	Landons Circle	Path between #210 & 214	Discontinuity	>1/4" change of level	
Landons Circle	Outer Circle	Landons Circle	#222	Discontinuity	Sewer Lid in path	
Landons Circle	Outer Circle	Landons Circle	Entrance to Walking Trail	Ramp Slope	Running slopes >5.0%	
Landons Circle	Outer Circle	Landons Circle	Entrance to Walking Trail	Detectable Warning Surface	Not present	
Landons Circle	Outer Circle	Landons Circle	Multiple Driveways	Driveway Slope	Cross slope >2.0%	
Larkspur Court	North-East	Tyree Springs Road to Meadowbrook Lane	10' from start of segment	Discontinuity	>1/4" change of level, electrical box	
Larkspur Court	North-East	Tyree Springs Road to Meadowbrook Lane	70' from 128 Larkspur	Discontinuity	>1/4" change of level, Broken Section	
Larkspur Court	North-East	Tyree Springs Road to Meadowbrook Lane	#122, 116, 104, Driveways	Driveway Slope	Cross slope >2.0%	
Lola Lane	Inner Circle	Riley to 305 Lola Lane	#237Driveway	Driveway Slope	Cross slope >2.0%	
Lola Lane	Outer Circle	Riley to 305 Lola Lane	#220,236,345,325 Driveways	Driveway Slope	Cross slope >2.0%	
Magnolia Drive	South	100 Magnolia Dr. to Sycamore Dr.	592' of path	Width	Handicap 5 x 5 passing spaces not provided every 200' (SW width <5.0')	
Magnolia Drive	South	100 Magnolia Dr. to Sycamore Dr.	Parallel Curb Ramps at Hunterwood Dr.	Detectable Warning Surface	Not present, slopes and discontinuities	
Magnolia Drive	South	100 Magnolia Dr. to Sycamore Dr.	Multiple discontinuities throughout path	Discontinuity	>1/4" change of level and broken or cracked path	
Meadowbrook Lane	North-West	Patana Dr. to Larkspur Ct.	60' before #100 Meadowbrook	Discontinuity	Sewer Lid in path	
Meadowbrook Lane	North-West	Patana Dr. to Larkspur Ct.	35' past #108 Meadowbrook	Discontinuity	Sewer Lid in path	
Meadowbrook Lane	North-West	Patana Dr. to Larkspur Ct.	#200 Driveway	Driveway Slope	Cross slope >2.0%	
Meadows Road	North	White House High School to end of Segment	All WHHS Driveways	Ramp Slopes	Running slopes >5.0% both sides of each driveway	
Millstone Way	South	116 Millstone Way	40' before #110 Drive, right side of Drive	Discontinuity	>1/4" change of level	
Morgan Trace Court	South	204 Morgan Trace Ct. to N. Palmers Chapel Road	perpendicular Curb Ramp at Clarice	Firm, Stable	Mud & loose gravel covering ramp	
Patana Drive	East	217 Patana Dr. to Meadows Road	#313,309,213,209,205,201,113,109, 105, 101 Driveways	Driveway Slope	Cross slope >2.0%	
Patana Drive	East	217 Patana Dr. to Meadows Road	10' before #113 Patana Dr.	Discontinuity	>1/4" change of level, water valve	
Pleasant Lane	North	120 Pleasant Ln to Patana Drive	669' of path	Width	Handicap 5 x 5 passing spaces not provided every 200' (SW width <5.0')	
Pleasant Lane	North	120 Pleasant Ln to Patana Drive	669' of path	Slope	Cross slope >2.0%	
Pleasant Lane	North	120 Pleasant Ln to Patana Drive	#116,112,108,104 Driveways	Driveway Slope	Cross slope >2.0%	
Raymond Hirsch Pkwy	South	31W to 538 Raymond Hirsch Pkwy.	175' of path	Slope	Cross slope >2.0%	
Raymond Hirsch Pkwy	South	31W to 538 Raymond Hirsch Pkwy.		Firm, Stable	Several curbs breaks producing rubble/gravel on SW surface	
Raymond Hirsch Pkwy	South	31W to 538 Raymond Hirsch Pkwy.	Green Sumner Co. Sign	Discontinuity	>1/4" change of level, Cracks	
Raymond Hirsch Pkwy	South	31W to 538 Raymond Hirsch Pkwy.	Opposite First TN Bank Bldg. Sign	Discontinuity	>1/4" change of level, Broken Section	
Raymond Hirsch Pkwy	South	31W to 538 Raymond Hirsch Pkwy.	First TN Bank Entrance & Exit Driveways	Ramp Slopes	Running slopes >5.0% both sides of each driveway	
Roaden Court	West	125 Roaden to Marlin Road	864' of path	Width	Handicap 5 x 5 passing spaces not provided every 200' (SW width <5.0')	
Roaden Court	West	125 Roaden to Marlin Road	864' of path	Slope	Cross slope >2.0%	
Roaden Court	West	125 Roaden to Marlin Road	#101, 105, 113, 117, &121 Driveways	Discontinuity	>1/4" change of level, Cracks	
Roaden Court	West	125 Roaden to Marlin Road	#117	Obstruction	Overhanging tree limbs near mailbox	
Roaden Court	West	125 Roaden to Marlin Road	#101, 105, 109,113, 117, 121 Driveways	Ramp Slopes	Running slopes >5.0% both sides of each driveway	
Sapphire Drive	South	106 Sapphire Dr. to Bedrock Dr.	Sapphire Dr. & Fieldstone	Discontinuity	Sewer Lid in path	
Sheffield Drive	S-E-N Loop	422 Sheffield Dr. to Chandler Blvd.	Multiple Driveways	Driveway Slope	Cross slope >2.0%	
Sheffield Drive	S-E-N Loop	422 Sheffield Dr. to Chandler Blvd.	Multiple Driveways	Driveway Slope	Running slopes >5.0% both sides of each driveway	

Section E-White House-ADA Sidewalk Inventory

East of US 31W, South of SR 76

Street Name	Sidewalk Side	Start/End/Location	Length/Location	Deficiency Type	Deficiency Notes/Observations	Completion Date
Sheffield Drive	S-E-N Loop	422 Sheffield Dr. to Chandler Blvd.	Multiple Driveways	Discontinuity	>1/4" change of level Either side of driveways	
Sheffield Drive	S-E-N Loop	422 Sheffield Dr. to Chandler Blvd.	#420, 216, 108 Paths	Discontinuity	>1/4" change of level Sewer and Water Valves	
Sheffield Drive	S-E-N Loop	422 Sheffield Dr. to Chandler Blvd.	Parallel Curb Ramp at Chandler, #108	Detectable Warning Surface	Not present, curb blocks ramp to Chandler	
Slate Court	West	110 Slate to Fieldstone Dr.	#110 behind mailbox	Discontinuity	>1/4" change of level	
Slate Court	West	110 Slate to Fieldstone Dr.	#110, 108 Driveways	Driveway Slope	Cross slope >2.0%	
Slate Court	West	110 Slate to Fieldstone Dr.	#104	Firm, Stable	Loose gravel either side of driveway	
Strassle Drive	West	132 Strassle to Meaows Road	#128,120,116,112,108,106,100 Driveways	Driveway Slope	Cross slope >2.0%	
Strassle Drive	West	132 Strassle to Meaows Road	Est 700' of path	Slope	Cross slope >2.0%	
Sycamore Drive	West	122 Sycamore Dr. to 204 Sycamore Dr.	Est 400' of path	Width	Handicap 5 x 5 passing spaces not provided every 200' (SW width <5.0')	
Sycamore Drive	West	122 Sycamore Dr. to 204 Sycamore Dr.	#122	Discontinuity	Broken Concrete	
Sycamore Drive	West	122 Sycamore Dr. to 204 Sycamore Dr.	Path from #122 to Honeysuckle Dr.	Slope	Cross slope >2.0%	
Sycamore Drive	West	122 Sycamore Dr. to 204 Sycamore Dr.	#200	Obstruction	Mailbox	
Telavera Drive	South	116 Telavera to McCurdy Road	#122,128,132,140,148,180 Driveways	Driveway Slope	Cross slope >2.0%	
Telavera Drive	North	116 Telavera to McCurdy Road	#155,127,119 Driveways	Driveway Slope	Cross slope >2.0%	
Telavera Drive	North	116 Telavera to McCurdy Road	Path from #147 to 187	Slope	Cross slope >2.0%	
Telavera Drive	North	116 Telavera to McCurdy Road	Est. 193 feet from McCurdy Road	Ramp Slopes	Sidewalk transitions to asphalt parking, slopes, and ramps not compliant	
Thoroughbred Way	South	300 Thoroughbred Way to N. Palmers Chapel Road	Telephone Box at Grayson Ln	Discontinuity	>1/4" change of level from telephone box in path	
Thoroughbred Way	South	300 Thoroughbred Way to N. Palmers Chapel Road	25' after crossing Grayson	Slope	Cross slope >2.0%	
Thoroughbred Way	South	300 Thoroughbred Way to N. Palmers Chapel Road	#300, 218, 124, 120, 114 Driveways	Driveway Slope	Cross slope >2.0%	
Thoroughbred Way	South	300 Thoroughbred Way to N. Palmers Chapel Road	Between Chapman Dr. and N. Palmers	Discontinuities	>1/4" change of level , multiple	
Tison Lane	West	123 Tison Ln to S Palmers Chapel Road	#123, 107,117,103 Driveways	Driveway Slope	Cross slope >2.0%	
Tison Lane	West	123 Tison Ln to S Palmers Chapel Road	Path between 117 & 123	Obstruction	Bush overgrowth	
Topaz Court	Outer Circle	106 Topaz to Bedrock Dr.	perpendicular Curb Ramp at Bedrock	Detectable Warning Surface	Not present, slopes and discontinuities	

Section F-White House-ADA Sidewalk Inventory

SR 76 Corridor

Street Name	Sidewalk Side	Start/End/Location	Length/Location	Deficiency Type	Deficiency Notes/Observations	Completion Date
College Street	South	Highway 31W, East to Carmack Drive.	Est 500+ of path	Width	Handicap 5 x 5 passing spaces not provided every 200' (SW width <5.0')	
SR 76	South	Highway 31W, East to Carmack Drive.	Path from HWY 31W to Hobbs Center Ramp	Slope	Cross slope >2.0%	
SR 76	South	Highway 31W, East to Carmack Drive.	Ramp from Street Parking to Hobbs Center	Detectable Warning Surface	Not present, slopes and discontinuities	
SR 76	North	Carmack Drive West to Highway 31W.	Est 500+ of path	Width	Handicap 5 x 5 passing spaces not provided every 200' (SW width <5.0')	
SR 76	North	Carmack Drive West to Highway 31W.	Multiple Discontinuities throughout path	Discontinuity	>1/4" change in level and broken or cracked path	
SR 76	North	Carmack Drive West to Highway 31W.	Parallel Curb Ramps (3) on path	Detectable Warning Surface	Not present, slopes and discontinuities	
SR 76	North	Charles Drive to I-65 On-Ramp termination			Compliant	
SR 76	North	Wilkinson Drive to Charles Drive	Front of Zaxbys	Discontinuity	>1/4" change in level and broken or cracked path	
SR 76	North	Wilkinson Drive to Charles Drive	Front of Zaxbys	Slope	Running slope >5.0%	
SR 76	North	Eden Way to Wilkinson Drive	Est 400' of path	Width	Handicap 5 x 5 passing spaces not provided every 200' (SW width <5.0')	
SR 76	North	Eden Way to Wilkinson Drive	Entrance to Car Wash	Ramp Slope	Running slopes >5.0%	
SR 76	North	Eden Way to Wilkinson Drive	Entrance to Car Wash	Ramp Slope	Cross slope >2.0%	
SR 76	North	Eden Way to Wilkinson Drive	Entrance to Dentist #706	Ramp Slope	Running slopes >5.0%	
SR 76	North	Eden Way to Wilkinson Drive	Entrance to Dentist #706	Ramp Slope	Cross slope >2.0%	
SR 76	North	Eden Way to Wilkinson Drive	Storm Grate before Wilkinson Dr.	Slope	Running slope >5.0%	
SR 76	North	Lone Oak to Eden Way	Est 1100' of path	Width	Handicap 5 x 5 passing spaces not provided every 200' (SW width <5.0')	
SR 76	North	Lone Oak to Eden Way	Corner of Hwy 76 and Lone Oak	Obstruction	Utility Pole in Path	
SR 76	North	Byrum Dr. (Kroger) to Lone Oak	Est 1300' of path	Width	Handicap 5 x 5 passing spaces not provided every 200' (SW width <5.0')	
SR 76	North	Byrum Dr. (Kroger) to Lone Oak	Multiple Discontinuities throughout path	Discontinuity	>1/4" change in level and broken or cracked path	
SR 76	North	Byrum Dr. (Kroger) to Lone Oak	Est 1300' of path	Slope	Cross slope >2.0%	
SR 76	North	Byrum Dr. (Kroger) to Lone Oak	Front of F&M Bank	Discontinuity	>1/4" change in level, Footprint in cement	
SR 76	North	Byrum Dr. (Kroger) to Lone Oak	Front of Dairy Queen	Discontinuity	>1/4" change in level, Storm Grate	
SR 76	North	Byrum Dr. (Kroger) to Lone Oak	End of Path (Lone Oak)	Discontinuity	>1/4" change in level and broken or cracked path	
Byrum Drive	West	Byrum Drive			Compliant	
SR 76	North	412 SR 76 to Byrum Drive	Entrance to Stadium Drive	Discontinuity	>1/4" change in level and broken or cracked path	
SR 76	North	Highway 31W to 110 SR 76	Est 250' of path	Width	Handicap 5 x 5 passing spaces not provided every 200' (SW width <5.0')	
SR 76	North	Highway 31W to 110 SR 76	Front of Mapco	Discontinuity	>1/4" change in level, Storm Grate	
SR 76	North	Highway 31W to 110 SR 76	Driveway to 110 HWY 76	Firm, Stable	Grass overgrowth, mud & loose gravel covering path	
SR 76	North	Highway 31W to 110 SR 76	Driveway to 110 HWY 76	Firm, Stable	Grass overgrowth, mud & loose gravel covering path	
SR 76	North	Highway 31W to 110 SR 76	Entrance to Mapco (2) and 110 HWY 76	Ramp Slope	Cross slope >2.0%	
SR 76	South	Raymond Hirsch to N. Sage Road	Est 2500' of path	Width	Handicap 5 x 5 passing spaces not provided every 200' (SW width <5.0')	
SR 76	South	Raymond Hirsch to N. Sage Road	Entrance to Speedway Gas	Ramp Slope	Running slopes >5.0%	
SR 76	South	Raymond Hirsch to N. Sage Road	Entrance to Speedway Gas	Ramp Slope	Cross slope >2.0%	
SR 76	South	Raymond Hirsch to N. Sage Road	Entrance to Speedway Gas	Discontinuity	>1/4" change in level and broken or cracked path	
SR 76	South	N. Sage Road to Hester Lane	Est 1000' of path	Width	Handicap 5 x 5 passing spaces not provided every 200' (SW width <5.0')	
SR 76	South	N. Sage Road to Hester Lane	Entrances to Shell Gas Station	Ramp Slope	Running slopes >5.0%	
SR 76	South	N. Sage Road to Hester Lane	Entrances to Shell Gas Station	Ramp Slope	Cross slope >2.0%	
SR 76	South	N. Sage Road to Hester Lane	Entrances to Nervous Charlies	Ramp Slope	Running slopes >5.0%	
SR 76	South	N. Sage Road to Hester Lane	Entrances to Nervous Charlies	Ramp Slope	Cross slope >2.0%	
SR 76	South	N. Sage Road to Hester Lane	Entrances to A&W	Ramp Slope	Running slopes >5.0%	
SR 76	South	N. Sage Road to Hester Lane	Entrances to A&W	Ramp Slope	Cross slope >2.0%	
SR 76	South	Hester Lane to I-65 Off-Ramp	Initial 75' from Hester Drive	Slope	Cross slope >2.0%	
SR 76	South	West Drive to Raymond Hirsch Pwky			Compliant	
SR 76	South	301 HWY 76 to West Drive	#317	Discontinuity	Water Valve in Path>1/4" change in level	
SR 76	South	HWY 31W to Elementary Drive	Entrance to Marathon Gas	Discontinuity	Electrical Box in Path>1/4" change in level	
SR 76	South	HWY 31W to Elementary Drive	Multiple Discontinuities throughout path	Discontinuity	>1/4" change in level and broken or cracked path	
SR 76	South	HWY 31W to Elementary Drive	Entrances to Marathon Gas	Ramp Slope	Running slopes >5.0%	
SR 76	South	HWY 31W to Elementary Drive	Entrances to Marathon Gas	Ramp Slope	Cross slope >2.0%	
SR 76	South	HWY 31W to Elementary Drive	#113	Obstruction	Mail Box and Mailbox Sign	

Section G-White House-ADA Sidewalk Inventory

US 31W Corridor

Street Name	Sidewalk Side	Start/End/Location	Length/Location	Deficiency Type	Deficiency Notes/Observations	Completion Date
US 31W	West	3313 31W South to HWY 76 (Advanced Auto Parts)	Est 935' (entire path)	Firm, Stable	Grass overgrowth, mud & loose gravel covering path	
US 31W	West	3313 31W South to HWY 76 (Advanced Auto Parts)	Multiple Discontinuities throughout path	Discontinuity	>1/4" change in level and broken or cracked path	
US 31W	West	3313 31W South to HWY 76 (Advanced Auto Parts)	WHUD Driveway, Sidewalk	Driveway Slope	Running slopes >5.0% both sides of each driveway	
US 31W	West	3313 31W South to HWY 76 (Advanced Auto Parts)	WHUD Driveway, Sidewalk	Driveway Slope	Cross slope >2.0%	
US 31W	West	3313 31W South to HWY 76 (Advanced Auto Parts)	South of #3219	Missing Section	Sidewalk Section missing from Path	
US 31W	West	3313 31W South to HWY 76 (Advanced Auto Parts)	Est 100' from Advanced Auto	Discontinuity	Section transitions to Asphalt, Broken and Rough	
US 31W	West	HWY 76 South to 3037 31W	558' (from #3047 to end of Segment)	Width	Handicap 5 x 5 passing spaces not provided every 200' (SW width <5.0')	
US 31W	West	HWY 76 South to 3037 31W	558' segment referenced above	Firm, Stable	Mud & loose gravel and grass covering path	
US 31W	West	HWY 76 South to 3037 31W	558' segment referenced above	Slope	Cross slope >2.0%	
US 31W	East	HWY 76 College Street to Clearview Apts			Compliant	
US 31W	East	Cliff Garrett Drive to HWY 76 College Street			Compliant	
US 31W	East	James K. Polk Trailhead to Cliff Garrett Dr.			Compliant	