June 14, 2021

MEMORANDUM

To: City of White House Stormwater Advisory Board

From: Derek Watson, City Recorder

Re: Meeting of the Stormwater Advisory Board

The Stormwater Advisory Board of the City of White House will meet on Monday, June 14, 2021. The meeting will take place at 4:00 pm in the Boardroom of the Billy S. Hobbs Municipal Center located at 105 College Street.

If you have any questions or are unable to attend please contact me at 615-672-4350, ext. 2111.



CITY OF WHITE HOUSE Stormwater Advisory Board Agenda June 14, 2021 4:00 p.m.

- I. Call to Order by Chairman
- II. Roll Call
- III. Adoption of the Agenda
- IV. Approval of March 8, 2021 Meeting Minutes
- V. Reports
- VI. New Business or Discussion Items
 - a. Current Stormwater Project
 - b. Nominations for chair and vice-chair positions (1-year term)
 - c. Voting for chair and vice-chair positions (1-year term)
- VII. Other Business
- VIII. Adjournment

CITY OF WHITE HOUSE

Stormwater Advisory Board Minutes March 8, 2021 4:00 p.m.

| I. | Call to | Order | by | Chairman |
|----|---------|-------|----|----------|
| | | | | |

Meeting was called to order at 4:01pm by Chairman Ceagus Clark.

II. Roll Call

Ald. Clif Hutson - Present; Mr. Gerald Herman - Present; Mr. Andy Cieslak - Present; Mr. Drew Christenson - Absent; Mr. Ceagus Clark - Present; Mr. Rob Dorris - Present; Mr. Jason Barnes - Present; **Quorum - Present.**

III. Adoption of the Agenda

Motion was made by Ald. Hutson, second by Mr. Barnes to approve the agenda. A voice vote was called for with all members voting aye. **Motion passed.**

IV. Approval of December 14, 2020 Meeting Minutes

Motion was made by Mr. Herman, second by Mr. Cieslak to approve the minutes from the December 14, 2020 meeting. A voice vote was called for with all members voting aye. **December 14, 2020 minutes were approved.**

V. Reports

Motion was made by Ald. Hutson, second by Mr. Barnes to approve the reports. A voice vote was called for with all members voting aye. **Motion passed.**


- VI. New Business or Discussion Items
 - a. Current Stormwater Project List


Stormwater Manager Aujuah Jackson was present and reviewed stormwater projects that have been completed in White House since the last Board meeting.

- VII. Other Business
 - a. None
- VIII. Adjournment

Meeting adjourned at 5:32 pm.

| | ATTEST: |
|---------------------------|-----------------------------|
| | |
| Ceagus Clark, Chairperson | Derek Watson, City Recorder |





Stormwater Project List

Our objective is to establish and maintain a proactive approach to minimize any potential for localized flooding within City limits. This includes but is not limited to ditch maintenance. In addition, a large part of this objective is to respond to citizen complaints in a timely manner.

Below are the departments top priorities and work summaries:

| Address | Scope of Work | Status | Notes |
|--------------------------------|--------------------------------------------------------------------|--------------------------------------|-------|
| Fields at Oakwood | Erosion Inspection | Work Order: 022521009 Complete | |
| 676 North Palmers Chapel | Single family residential' inspection of driveway culvert | W/O # 022521006 Complete | |

W.

| 212 Hobbs Drive | Driveway replacement; extend culvert 14ft using corrugated metal pipe in ROW; replace headwall | WO#- 021021007 Complete | |
|------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------|--|
| 103 Spicer Court | Increased infrastructure elevation and excavated material from conveyance in ROW; redressed with seed & straw | WO# - 020921001 Complete | |
| Rainfall | Most recent rain event occurred on weekend of February 26 th -28 th . The City received approximately 5.41 inches of rain. | 7 complaints received. 2 determined for residential flooding. Calista pond is undergoing dewatering and Villages is scheduled for CIP. | |

| 100 Oak Park Ct. | Replace headwall and culvert | WO# - 020221001 Complete | |
|----------------------------|----------------------------------------------------------------------------------------------------------------------|--------------------------------|--|
| North Palmers Chapel | Open trench inspection for new drainage system at the Reserve at Palmers Crossings for phase 2. | WO# - 020321001 Complete | |

SWEEPER LOG

Monthly Report

4 cu.yd hopper/ actual usage- 3.0 cu.yd=4.5 tons


| Date | Time | Mileage | Tons | Streets |
|----------|------|---------|------|-----------------------------------------------|
| 02/24/21 | 8 | 30 | 9 | Hwy 76, Raymond Hirsch, College St, 31W South |
| 02/25/21 | 4 | 21 | 4 | 31W North and South |
| Totals: | 12 | 54 | 13 | (detailed listing of all streets on file) |


Stormwater Division

| Total Hours Worked | FY 15/16 | FY 19/20 | 31-Dec | 31-Jan | 28-Feb | YTD 20/21 |
|----------------------|----------|----------|--------|--------|--------|-----------|
| Stormwater | 5,744 | 7,204 | 982 | 832 | 853 | 7531 |
| Work Orders | 0 | 69 | 11 | 4 | 13 | 96 |
| Overtime | 508.5 | 262 | 26 | 6 | 23 | 137 |
| Facility Maintenance | 3,494 | 638 | 107 | 85 | 112 | 464 |
| Fleet Maintenance | 1,034 | 314 | 74 | 107 | 94 | 473 |
| Administrative | 385 | 1,138 | 116 | 145 | 128 | 1127 |
| Drainage Work (feet) | 0 | 3,988 | 545 | 116 | 510 | 2576 |
| Drainage Man Hours | 0 | 1,371 | 228 | 139 | 163 | 2002 |
| Debris Removed Load | 0 | 188 | 6 | 6 | 6 | 164 |
| Sweeping Man Hours | 0 | 309 | 26 | 34 | 21 | 207 |
| Mowing Hours | 0 | 102 | 0 | 0 | 0 | 3 |
| R-O-W Hours | 0 | 1,506 | 57 | 48 | 10 | 166 |
| Shoulder/Curb Hrs | 0 | 0 | 0 | 0 | 0 | 40 |

The Stormwater crew assisted Public Work salting and plowing the roadway between February 15^{th} - 21^{st} . There was a total of **79 salt hours worked**.

| Catch Basin: Object ID: | Neighborhood | Location: | Date: |
|----------------------------|--------------|----------------|----------|
| 456/457 | Northwoods | Pinewood | 02/24/21 |
| 146 | Northwoods | Magnolia | 02/24/21 |
| 147 | Northwoods | Magnolia | 02/24/21 |
| 58 | Northwoods | Hunterwood | 02/24/21 |
| 465/466 | Northwoods | Hunterwood | 02/24/21 |
| 450 | Northwoods | Hunterwood | 02/24/21 |
| 136 | Northwoods | Pembrooke | 02/24/21 |
| 135 | Northwoods | Pembrooke | 02/24/21 |
| 120 | Northwoods | Highland | 02/24/21 |
| 122 | Northwoods | Highland | 02/24/21 |
| 123 | Northwoods | Highland | 02/24/21 |
| 121 | Northwoods | Timberwood | 02/24/21 |
| 118 | Northwoods | Hunterwood Ct. | 02/24/21 |





Stormwater Project List

Our objective is to establish and maintain a proactive approach to minimize any potential for localized flooding within City limits. This includes but is not limited to ditch maintenance. In addition, a large part of this objective is to respond to citizen complaints in a timely manner.

Below are the work order requests and summaries that have been completed:

| Address | Scope of Work | Status | Notes |
|-----------------------|-------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------|-------|
| 210 Robert Ave. | Ditch rehabilitation from 201- 214. Redistributed extracted soil to back fill and stabilize embankment s | Work Order: 030321001 Complete | |
| 311 Hobbs Dr. | Stabilized driveway culvert | W/O # 031121003 Complete | |

| 341 Aller Drive | Rehabilitated cross drain and stabilized ditch line to counter excessive erosion. | WO#- 042320009 Complete | |
|------------------------------|----------------------------------------------------------------------------------------------------|--------------------------------|--|
| 100 & 101 Hobbs Dr. | Removed Built up sediment, re- shaped ditch line, installed Rip rap in areas to slow the velocity. | WO# - 031121002 Complete | |

| Rainfall | Most recent rain event occurred on weekend of March 27 th and 28 ^{th.} The City received approximatel y 4.55 inches of rain for the month of March. | 2 NEW complaints received. | |
|-----------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|--|
| Issues | 300 Orchard Park Dr 110 Beechbrook Ct. | Scheduled for June | |
| Calista Pond | Dewatered on 03/26 and 03/30 | Removed 67,800 gallons of water to prevent localized flooding WO# 030121019 Complete | |

WO#03302100 101-173 Highlan d Drive Re-defining 1 ditch Complete Removeddebris and obstructions WO# -135 Villages Court from 030121016 headwall causing Complete ponding during heavy rain events.

Stormwater Division

| Total Hours Worked | FY 15/16 | FY 19/20 | 31-Jan | 28-Feb | 31-Feb | YTD 20/21 |
|-------------------------|-------------|-------------|--------|--------|--------|-----------|
| Stormwater | 5,744 | 7,204 | 832 | 853 | 974 | 8508 |
| Work Orders | 0 | 69 | 4 | 13 | 18 | 114 |
| Overtime | 508.5 | 262 | 6 | 23 | 10 | 147 |
| Facility Maintenance | 3,494 | 638 | 85 | 112 | 42 | 506 |
| Fleet Maintenance | 1,034 | 314 | 107 | 94 | 82 | 505 |
| Administrative | 385 | 1,138 | 145 | 128 | 174 | 1301 |
| Drainage Work (feet) | 0 | 3,988 | 116 | 510 | 1400 | 3976 |
| Drainage Man Hours | 0 | 1,371 | 139 | 163 | 387 | 2389 |
| Debris Removed Load | 0 | 188 | 6 | 6 | 11 | 175 |
| Sweeping Man Hours | 0 | 309 | 34 | 21 | 14 | 221 |
| Mowing Hours | 0 | 102 | 0 | 0 | 0 | 3 |
| R-O-W Hours | 0 | 1,506 | 48 | 10 | 18 | 184 |
| Shoulder/Curb Hrs | 0 | 0 | 0 | 0 | 0 | 40 |

SWEEPER LOG


Monthly Report

4 cu.yd hopper/ actual usage- 3.0 cu.yd=4.5 tons

| Date | Time | Mileage | Tons | Streets |
|----------|------|---------|------|-------------------------------------------|
| 03/11/21 | 3 | 12 | 4.5 | Orchard Park and Hampton Village |
| Totals: | 3 | 12 | 4.5 | (detailed listing of all streets on file) |

Catch Basin Cleaning

| Work Order # | Neighborhood | Location: | Date: |
|--------------|----------------------|----------------------|----------|
| 033121005 | | Villages Ct. | 03/31/21 |
| 033121005 | | Apache Trail | 03/31/21 |
| 033121005 | | S. Aztec Dr. | 03/31/21 |
| 033121005 | | Heritage Dr. | 03/31/21 |
| 033121005 | | Whitson Ct. | 03/31/21 |
| 033121005 | | Hobbs Dr. | 03/31/21 |
| 033121005 | | N. Palmers Chapel | 03/31/21 |
| 033121005 | Covington Heights | Covington Bend | 03/31/21 |
| 033121005 | | Sumner Crossings | 02/24/21 |
| 033121005 | | Strassle Dr | 03/31/21 |
| 033121005 | | Brooklawn | 03/31/21 |
| 033121005 | Orchard Park | Cherry Lane | 02/24/21 |
| 033121005 | Holly Tree | Willowleaf Ln | 02/24/21 |



Directors Notes

- No new stormwater complaints have been reported.
- Incident: Employee sustained bodily injury from impact with tree limb during routine vegetation maintenance. Reported on 04/28 and cleared for duty on 05/03.
- On April 22nd, The City issued 4 fence removal letters to residents in the Northwoods Subdivision. Chain linked fencing is located within the City easement and obstruct runoff. Work order has been generated to rehabilitate the swales in that area and route drainage to retention pond.
- The City was nominated for a public education and outreach award. This stems from recognition of the departments' participation in the tree giveaway and WOW newsletter that aids to empower the public and reduce stormwater pollution.
- On April 27th, a new fee schedule was proposed for land disturbance/grading to City Administrator and Planning and Codes Director. Study session scheduled for August 19th with BMA.
- Grading permits have been approved for Doris Farms and Lennar Homes: Willow Springs and Willow Grove.
- Streamside salamander was impacted by sediment from Fields of Oakwood subdivision development. Developers will be issued a notice of non-compliance and TDEC and TWRA will schedule a site visit.
- On April 22nd, we have requested a bid proposal from CSR in preparation of the Springbrook drainage improvement project.
- Legacy Farms have submitted mass grading revisions for Phase 2 which are currently under review.

Stormwater Project List

Our objective is to establish and maintain a proactive approach to minimize any potential for localized flooding within City limits. This includes but is not limited to ditch maintenance. In addition, a large part of this objective is to respond to citizen complaints in a timely manner.

Below are the work order requests and summaries that have been completed for the month of April:

| Address | Scope of Work | Status | Notes |
|-------------------------|-------------------------------------------------------------------------------------------------------|--------------------------------------|-------|
| 102 Bridlewood Court | Excavated ditch to appropriate slope from Laura Drive to Bridlewood and stabilized for positive flow. | Work Order: 041221003 Complete | |

| 223 Rolling Acres Drive | Illicit Discharge – sump pump | Work Order: 040521003 Complete | |
|----------------------------|----------------------------------------------------------------------------|--------------------------------------|--|
| 309 Valley View Drive. | Undergrowth and vegetation extracted from conveyance and repaired washouts | W/O # 041221003 Complete | |

| 524 North Palmers Chapel Road | Pave secondary entrance to the Reserve. Sheet flow impacting downstream neighbors. Future widening project to route discharge to Honey Run Creek | WO#- 040421006 Complete | |
|-------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------|--|
| Fields of Oakwood | Stormwater construction inspection for erosion control | ongoing | |
| The Parks | Open trench inspection | WO#- 040721008 Complete | |

| 100 Baylee Court | Installed 30' of 12" ADS into existing catch basin. | WO# - 040721001 Complete | |
|--------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------|--|
| 403 Autumn Wood Drive | Repaired voids in homeowners' yard. Excavated excess and built-up fill obstructing conveyance. Bare areas stabilized. Culverts jetted to efficacy. | WO# - 040521007 Complete | |

Stormwater Division

| Total Hours Worked | FY 15/16 | FY 19/20 | 31-Mar | 30-Apr | YTD 20/21 |
|-------------------------|-------------|-------------|--------|--------|-----------|
| Stormwater | 5,744 | 7,204 | 974 | 899 | 9404 |
| Work Orders | 0 | 69 | 18 | 15 | 129 |
| Overtime | 508.5 | 262 | 10 | 15 | 162 |
| Facility Maintenance | 3,494 | 638 | 42 | 15 | 521 |
| Fleet Maintenance | 1,034 | 314 | 82 | 83 | 638 |
| Administrative | 385 | 1,138 | 174 | 207 | 1508 |
| Drainage Work (feet) | 0 | 3,988 | 1400 | 925 | 4901 |
| Drainage Man Hours | 0 | 1,371 | 387 | 375 | 2764 |
| Debris Removed Load | 0 | 188 | 11 | 10 | 185 |
| Sweeping Man Hours | 0 | 309 | 14 | 140 | 361 |
| Mowing Hours | 0 | 102 | 0 | 18 | 21 |
| R-O-W Hours | 0 | 1,506 | 18 | 0 | 184 |
| Shoulder/Curb Hrs. | 0 | 0 | 0 | 0 | 40 |

SWEEPER LOG

Monthly Report

4 cu.yd hopper/ actual usage- 3.0 cu.yd=4.5 tons

| Date | Time | Mileage | Tons | Cons Subdivision / Street | |
|----------|------|---------|------|-----------------------------------------------|--|
| 04/01/21 | 18 | 39 | 6 | 31W S, Meadowbrook, RHPK, Bridle Creek | |
| 04/12/21 | 18 | 25 | 9 | Beechbrook, Springbrook, 31W N | |
| 04/13/21 | 18 | 28 | 6 | Covington Heights, Heritage Farms, Tison Est. | |
| 04/14/21 | 18 | 31 | 6 | Highway 76, Briarwood, Kennedy, Walnut | |
| 04/15/21 | 18 | 25 | 6 | Highway 76, Soccer Complex, Greystone | |
| 04/21/21 | 18 | 12 | 6 | 6 Magnolia Village | |
| 04/22/21 | 18 | 24 | 6 | Holly Tree, Indian Ridge | |
| 04/26/21 | 18 | 19 | 6 | Indian Ridge, Northwoods | |
| 04/27/21 | 16 | 19 | 6 | Northwoods | |
| Totals: | 160 | 228 | 60 | | |

Right-of-Way Mowing

| Work Order # | Type of SCM | Location: | Date: |
|--------------|----------------|------------------------------|----------|
| 042721001 | Detention Pond | North Palmers Chapel Road | 04/26/21 |
| 042721001 | Detention Pond | Shady Lane | 04/27/21 |

Stormwater Project List

Our objective is to establish and maintain a proactive approach to minimize any potential for localized flooding within City limits. This includes but is not limited to ditch maintenance, right of way mowing, and infrastructure improvements. In addition, a large part of this objective is to respond to citizen complaints in a timely manner.

Please be advised that this is an operative working list. It is organized to transition based on feasibility and severity. This list is subject to change at the discretion of the Stormwater Manager, Public Services Director or City Administrator. Please notify your supervisor when projects are complete or if any materials are needed to complete a particular project.

| Address | Scope of Work | Status | Comments / Notes |
|---------------------|------------------------------------------------------------------------------------|---------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 612 Calista Rd. | Re-channel ditch line to divert water off property with infrastructure | ⊠Complete Date: 10/05/20 ⊠Photos | WO: 08312005: The team had to remove an existing headwall at the cross drain to connect to the infrastructure and set a junction box to also intercept a newly installed cross drain from the neighborhood of Fields of Oakwood. After the team removed the 24" headwall from Calista's cross drain, we connected 4 feet of 24' RCP and inserted into the junction box. Then the team connected 20' of 15" to the cross drain from fields of Oakwood and inserted it into the junction box. Then 104' of the 24" discharge line was installed to carry the storm water east into the property to discharge off site into a channel that was developed per plans by Land Development for the neighborhood of Fields of Oakwood. |
| 212 Hillwood Dr. | Establish swale off driveway to channel water downstream | ⊠Complete Date: 12/14/2020 ⊠Photos | Extended existing driveway pipe to divert runoff from property |
| 120 Strassle Dr. | Repair damages in infrastructure; upgrade piping | ⊠Complete Date: 12/15/2020 ⊠Photos | The team removed the concrete box and a 20' section of the 24" pipe and replaced with 1 24" Nyloplast drop inlet and 17' of 24" HDPE pipe with 3 24" couplers. The team took extra precautions with a soil tight seal at each joint with the couplers by installing a section of 6 oz geotextile fabric around the joints to ensure that soil could not enter the infrastructure. |

| | | | The pipe and structure was bedded in 3/4"stone and backfilled with the same sized stone to support the pipe to the spring line/ hunch and then backfilled with soil to existing grade. The team imported 10 tons of 3/4" stone and exported 1.5 loads of excess soil then stabilized with contractor blend seed and mulched with 5 bales of straw and 1 roll of straw matting. |
|---------------------------|-----------------------------------------------------------------|-----------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 212 Morgan Trace Ct. | Divert inflow to existing drainage system | ⊠ Complete Date: 08/27/2020 ⊠ Photos | work order number 082420001 The team began their operation by removing thick vegetation and trees to gain access to the conveyance and detention pond. After removing all the undergrowth and trees, the team discovered that there was several rock check dams and silt fence still in place in the conveyance and alongside the detention area from development of the site and was successfully removed in order to allow the watershed to be continuous to the outfall structure. After the team regraded the conveyance, pond banks and the rear property of 212 (behind porch) with imported topsoil, all bare areas were stabilized with seed along with double net straw matting on the slopes and loose straw on the flat areas. |
| 3123 Pleasant Grove Rd | Install 2 turn lanes at intersection of Hwy 76 | ⊠ Complete Date: 08/15 ⊠ Photos | Curb and gutter to be installed week of 09/30 followed by paving |
| 112 Ravenwood Ct. | Repair damages in infrastructure; address disjoints | ⊠ Complete Date: 11/24/20 ⊠ Photos | Alleviate potholes in soil; seal inlet pipe to catch basin |
| 107 Copperfield Dr | Upgrade piping size in infrastructure to better convey runoff | □Complete Date: □Photos | Springbrook Subdivision – CCTV line requested; ongoing; scheduled for FY21-22 CIP |
| 612 Sage Rd | Remove excess | ⊠Complete | Up to Hampton Village |

| | soils in drainage conveyance | Date: 11/10/20 ⊠ Photos | |
|---------------------------|--------------------------------------------------|----------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 2500 HWY 31W | Repair drainage pipe for Super Stop Market | ☐Complete Date: ☐Photos | Owner must order parts. City will perform labor. Several attempts to contact owner and initiate project no response |
| 164 Honeysuckle Dr | Re-establish swale | ⊠Complete Date: 02/08/20201 ⊠Photos | Northwoods Catch basin cleaning Excavated sediment from inlet; verified positive flow (3") between inverts; ditch line rehabilitated and seeded with straw for repair |
| 122 Sycamore Dr | Re-establish swale | ⊠ Complete Date: 05/05/20 ⊠ Photos | We excavated the buildup material that was restricting the flow that and preventing the full use of volume for the storm drain infrastructure. |
| 209 Rolling Acres Dr | Re-establish swale | □Complete Date: □Photos | Northwoods |
| 215 Rolling Acres Dr | Re-establish swale | □Complete Date: □Photos | Northwoods |
| 301 Rolling Acres Dr | Re-establish swale | □Complete Date: □Photos | Northwoods |
| 102 Rolling Forrest Dr | Re-establish swale | □Complete Date: □Photos | Northwoods |
| 102-109 Bridlewood Dr. | Re-define swale in back yards | ⊠ Complete Date: 04/20/21 ⊠ Photos | ID <u>042021002</u> Excavated ditch to appropriate slope from Laura Dr. to Bridlewood. Grade work to move material 16.5 " in 275' and stabilized. |
| 341 Allers Dr | Rehabilitate cross drain/easement | ⊠ Complete Date: 04/28/2020 ⊠ Photos | WO:# 042320009 - Regraded ditch line for positive flow fill in and compacting washout locations. all excess soil extracted and reused to create earth berms on either side of ditch line |
| 408 Hunterwood Dr | Rehabilitate detention pond | □Complete Date: □Photos | |
| 160 Blueberry St | Ditch cleaning | □Complete Date: □Photos | Orchard Park; offsite improvement for future development; propose to CSR |

| 100 Baylee Ct | Upgrade drainage pipe; improve swale | ⊠Complete Date: 04/16/20 ⊠Photos | Off of SPC; upgraded 4" to 18" divert to existing infrastructure |
|-----------------------------|-------------------------------------------------------------------------|----------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 125 Brooklawn Dr | Re-establish swale | ⊠Complete Date: 05/24/21 ⊠Photos | Installed earth berm |
| | | | |
| 210 Beechbrook Ct | Re-establish swale | □Complete Date: □Photos | Off of SPC; ditch cleaning entire roadway |
| 218 South Palmers Chapel | Install catch basin within ROW | □Complete Date: □Photos | SPC; incorporate within Springbrook plan submittal |
| 149 Willowleaf Lane | Improve watershed; flooding from open field behind property | ⊠Complete Date: 05/24/21 ⊠Photos | ID <u>052421001</u> Earth berm to divert in line flow to house from off site to property line drainage easement. Imported 2 loads of topsoil. Graded back of property to divert watershed. Seed and straw to stabilize. |
| | | | |
| 103 Spicer Dr | Re-establish swale | ⊠Complete Date: 02/09/20201 ⊠Photos | Conveyance excavated in ROW to existing invert elevation from culvert to driveway. Excessive buildup and debris removed from cross drain. Homeowner requested soil. |
| 100 Oak Park Ct | Improve rip rap apron by roadway | ⊠Complete Date: 02/02/2021 ⊠Photos | Bedrock added to culvert and established up to ground level of roadway. Repaired gully erosion at orifice of outlet structure |
| 128 Oak Park Ct | Redefine easement between homes to Strassle Dr | □Complete Date: □Photos | Off of Meadows Ct. Residents should remove trees in easement |
| | | | |
| 100 – 102 Hobbs Dr | Re-establish swale | ⊠Complete Date: 03/10/21 ⊠Photos | WO# 031121002 - Culverts jetted to remove excess buildup of silt, reshaped ditch line, installed rip rap apron to slow velocity of runoff. |
| 205 Hobbs Dr | Re-establish swale | ⊠Complete Date: 01/07/2021 ⊠Photos | Ditch cleanout to inlet; Removed reel formation and positive flow to cross drain |
| 401 Hobbs Dr | Re-establish | ☐ Complete | Box culvert (csr report) |

| | swale | Date: | |
|---------------------------------------------|-----------------------------------------------------------------------------------|---------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 210 Spring St | Re-establish swale | □Complete Date: □Photos | Install 2 catch basins and 80ft pipe |
| | | | |
| 200 Covington Bend | Ditch cleaning; repair and/or clean out culvert | □Complete Date: □Photos | CIP |
| 309 Covington Bend | Re-establish swale; repair and/or cleanout culvert | □Complete Date: □Photos | CIP |
| 105 Winchester Ct | Rehabilitate drainage infrastructure to provide positive flow | □ Complete Date: □ Photos | CIP |
| | | | |
| 210-214 Robert Ave | Re-establish swale | ⊠Complete Date: 03/23/21 ⊠Photos | WO #: 030321001 - Removed built up material from culverts and drainage conveyance and installed 4 tons of class A for a rip rap apron, with fabric, at discharge point from the cul-de-sac. 03/23/21 - back-filled exposed fiber line 03/23/21- Jetted culverts as needed. |
| | | | |
| 214 Eastside Dr | Improve drainage and rehabilitate ditch line | ⊠Complete Date: 11/18/20 ⊠Photos | Installed and Elevated driveway culvert of property to reduce impact of flow from cross drain; concrete driveway replaced |
| | | | |
| 125 Villages Ct | Clean inlet channel and fill in ditch line as necessary | ⊠Complete Date: 09/21/20 ⊠Photos | Created an open channel for drainage; removed vegetation to allow natural flow of stream |
| 207 S Aztec Dr | Redefining ditch. Remove trees from 211 affecting drainage pathway | ⊠ Complete Date: 02/03/21 ⊠ Photos | Work Order # 010721001 The conveyance generates a significant amount of watershed and creates high velocity runoff. The effects of this watershed had eroded the swale creating voids and undermining the properties fencing in the area. The conveyance was excavated and Rip rap sized stone installed to control the |

| | | | velocity. The disturbed areas were stabilized with double net straw matting and baled straw with seed. |
|-----------------------|----------------------------------------------------------------------------|---------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 318 Walnut Ct | Re-establish swale and ditch cleaning | ⊠Complete Date: 12/17/2020 ⊠Photos | Work Order: 113020006 the pipe downstream from the culvert was undersized and restricting the flow rate causing the back flow. The team began to cut in a swale located on the left of the property from the driveway culvert to the wet weather conveyance, operating in the designated easement associated with this parcel. The Team was able to use the excavated soil form the newly installed conveyance system onsite to assist the homeowner with voids in the rear of the property and to provide the option to the property owner to use the soil as needed. |
| 100 Heritage Dr | Re-establish swale and extend wing wall | □Complete Date: □Photos | |
| | | | |
| 303 Hillwood Dr | Re-establish swale and apply rip rap to prevent wash outs | □Complete Date: □Photos | |
| | | | |
| 109 Meadows Ct | Re-establish swale and ditch cleaning | □ Complete Date: □ Photos | Conjunction with hickerson/Wilkinson CIP |
| 302 Valley View Rd | Install ROW drainage pipe between lots to alleviate open ditch | ⊠ Complete Date: 6/02/20 ⊠ Photos | The stormwater received a request to install drainage pipe in a conveyance to connect two driveways together and eliminate the open conveyance. Once lines where lowered we installed 36" HDPE drainage pipe and connected it to the existing culverts, backfilled half of the pipe with 1 load ¾" stone and imported 2 loads of Topsoil, graded and seed and straw bare soils. Installed a bag of concrete on damaged area drain grate to secure it to the infrastructure. |
| | | | |

| | upgrade infrastructure | Date: □Photos | |
|---------------------------|-------------------------------------------------------------------------------|---------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| | | | |
| | | | |
| 121 Industrial Dr | Re-establish swale | ⊠ Complete Date: 04/06/20 ⊠ Photos | Ease driveway flooding; 4 hours of Labor for 3 employees Dump Truck (removed 2 loads of fill material) Excavator 100' of ditch for double netting straw matting w/ 5 lbs. of contractor blend seed |
| 7016 Indian Ridge Blvd | Create conveyance within ditch to prevent erosion | ⊠Complete Date: 11/23/20 ⊠Photos | 102720001: Displace velocity of runoff; ditch rehabilitated from HW to existing concrete channel to offset erosion. The team began operations by trimming low lying branches from trees in the conveyance and then excavated the ditch line down 18 inches and 4 feet wide, 6-inch sides to anchor the 6 oz geo-textile fabric, and Installed 22 tons of Class A stone to displace the velocity being discharged into the conveyance. The bare soils after installation were seeded and straw |
| 229 Cherry Ln | Repair voids in soil and damaged underground infrastructure | ⊠ Complete Date: 05/06/21 ⊠ Photos | ID <u>090820007</u> : Excavated pipe and wrapped couplers with 4 oz geotextile fabric to prevent any soils from entering the infrastructure causing the voids in the yard. Pipe was found to have a separation from the coupler installed. Backfilled with the native soil and the team will import topsoil to preform the finish grade work when weather allows. |
| 403 Autumn Wood Dr | Define swale at culvert orifice; backfill sinkholes in front yard | ⊠ Complete Date: 04/08/21 ⊠ Photos | ID 040521007: removed the built up material from the conveyance and placed the excess material in a void in the homeowners yard per their request.stabilized the bare areas with seed a,straw and matting. discovered a 10" pvc pipe placed between the two drives to connect the 15' pipe culverts which was removed;Jetting culverts on 4/06; WHUD found leak on 05/24 and |

| | | | uncovered water meter. |
|-----------------------|----------------------------------------------------------------------------|-------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 538 NPC Rd. | Eroded embankments of creek impacting integrity of driveway | ⊠Complete Date: 01/07/21 ⊠Photos | The team removed the tree debris from along the conveyance that had been collecting at or near the culvert invert causing a blockage to the outfall. The blockage resulted in the water beginning redirected to sides of the culvert causing the soil material to become more susceptible to eroding. After the team removed the debris from the conveyance and exported 3 loads of material, the team imported 2 loads of compactable fill material to repair the void above the culvert. The team placed, compact the soil and stabilized the bank with seed and double net straw matting and lose straw. |
| 309 Valley View Dr | Rehabilitate channel | ⊠ Complete Date: 04/12/21 ⊠ Photos | ID <u>041221003</u> : Removed vegetative and aggregated undergrowth from channel. It is recommended to extend concrete flume. |